

UNITED STATES N. M. O. C. G. S. STATE  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. M-1 - 0503
2. NAME OF OPERATOR TEXACO INC. ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Well is located 2310' from the North line and 1920' from the West line.		8. FARM OR LEASE NAME Cotton Draw Unit
14. PERMIT NO. Regular		9. WELL NO. 68
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3457' (DF)		10. FIELD AND POOL, OR WILDCAT Paduca Morrow Gas
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12, T-25-S, R-31-E
		12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

REMARKS

- Well Status - TR-NG (To Be Reconditioned-Natural Gas)
- Temporary Abandonment Date - December 4, 1975
- Reason for Abandonment - Low gas production makes well uneconomical to produce.
- Future Plans - Remedial work to acidize Cotton Draw Unit No. 67 will start in the very near future. If remedial work proves to be successful, similar work will be performed on No. 68.
- Date of Future Workover or Plugging - 1976

RECEIVED

DEC 10 1975

O. C. C.  
ARTESIA, OFFICE

RECEIVED  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. District Supt.

DATE 12-5-75

(This space for Federal or State office use)

APPROVED BY

UNLESS FURTHER APPROVED, WELL MUST  
BE PUT TO BENEFICIAL USE OR PLUGGED BY  
APRIL - OCTOBER 1 - 1976

DATE

\*See Instructions on Reverse Side