

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN DUPLICATE
OTHER INFORMATION

Form approved
Bureau No. 42

6. LEASE DESIGNATION AND SERIAL

MI 0466137

8. IF INDIAN, ALLOTTEE OR TRUST

SUNDRY NOTICES AND REPORTS ON WELLS

(Check one: Initial on Form 1, Report on Form 2, or Report on Form 3. If on Form 1, check appropriate box for application for permit.)

RECEIVED

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Government Q

9. WELL NO.

1

10. FIELD AND POOL OR WHOLESALE
Undes. Washington
Ranch Morrow

11. SEC., T., R., S., OR BLK. AND
SURVEY OR AREA

Sec. 26-T256-R24E

1. NAME OF WELL OR OTHER Dry Hole

2. NAME OF OPERATOR

Cities Service Oil Company

MAR 2 1974

3. ADDRESS OF OPERATOR

Box 4906 - Midland, Texas 79701

4. LOCATION OF WELL OR part location clearly and in accordance with any state requirements

See also space 17 below
At Surface 1980' FSL & 660' FWL of Sec. 26-T256-R24E,
Eddy Co., New Mexico.

14. PERMIT NO.

30-015-20654

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3675' GR.

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

*Note: Report results of multiple completion on Well
Completion or Restoration Report and Log Form.

17. DESCRIBE PROPOSED OR CONTINUED OPERATION (Clearly state all pertinent details, and give pertinent data, including estimated date of completion of work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all sections and intervals pertinent to this work.)

T.D. 7200' Shale. Plugged & abandoned. This well was plugged & abandoned in the following manner:

1. Spotted a 50 sx cement plug @ 6900' - 6700'.
2. Spotted a 25 sx cement plug @ 5750' - 5650'.
3. Displaced a 50 sx cement plug @ 3800' - 3700'.
4. Displaced a 50 sx cement plug @ 2300' - 2200'.
5. Displaced a 60 sx cement plug @ 940' - 840' (1/2 in and 1/2 out of 13-3/8" casing set @ 839').
6. Displaced a 15 sx cement surface plug @ 20' - 0' w/ a 4" dry marker extending 4' above the ground to designate a plugged and abandoned location.
7. The location will be cleared of all equipment and debris and your office will be notified for final inspection.

This well was plugged on 9-15-73. USGS was notified but did not witness plugging.

I hereby certify that the foregoing is true and correct

SIGNED

Chandler

TITLE Region Oper. Mgr.

DATE Sept. 19, 1973

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side