		P. COSA	(-0-9	ry list,
Form 9-331 (May 1943)			Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NM 0457116	
(De not t	SUNDRY NOTICES AND REPORTS (use this form for proposals to drill or to deepen or pluguse "APPLICATION FOR PERMIT—" for such permits—" for such per		6. IF INDIAN, ALLOT	TEE OR TRIBS NAME
I. OIL WELL	GAS OTHER Dry	RECEIVEL	7. UNIT AGREEMENT	NAME
2. Name of Operator Midwest Oil Corporation 3. Address of Operator		8. FARM OR LEASS NAME Federal "O" 9. WELL NO.		
1500 Wilc 4. Indiation of V See also space At surface	o Building Midland, Temper location clearly and in accordance with any 17 below.) 1980' FNL & 1980' FEL	10. FIELD AND POOL, OR WILDCAT Wildcat 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA		
14. PERMIT NO.	15. ELEVATIONS (Show whether D	F. ET, GR, etc.)	11-26S-25E 12. COUNTY OR PAR.	ISH 13. STATE
<u>50-01</u>	Check Appropriate Box To Indicate N	Natura of Natica Report or C	l Eddy Other Data	New Mexico
nent to this	NOTICE OF INTENTION TO: SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS POSED OR COMPLETED OPERATIONS (Clearly state all pertiner work. If well is directionally drilled, give subsurface loss work.)* Set the following cmt plugs - Hall	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results Completion or Recompletion or Recompletion or Recompletion and dates, and give pertinent dates, and measured and true vertical	REPAIRIN ALTERING ABANDON of multiple completietion Report and Log	on on Well
	33 sx - 100' @ 1650 - 1750 33 sx - 100' @ 900 - 1000 33 sx - 100' @ 150 - 250 10 sx @ surface			:
	Well P & A.			
	·	Here here		
,	by that the foregoing is true and correct	Production Clerk	DATE 11-	14-73

*See Instructions on Reverse Side