Cut 7 5/8" csg. @ 5040'. Rec. 113 jts. 2.

3. Set cmt. plugs as follows:

> 5550-5650 100' 3250-3350 100' 1600-1700 1001 20 sx. at surface.

4. Weld cap of csg.

Form 9-331 (May 1963)

WELL

14. PERMIT NO.

16.

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

TEST WATER SHUT-OFF

FRACTURE TREAT

REPAIR WELL

(Other)

SHOOT OR ACIDIZE

GAS WELL

XX

OTHER

Set 4: pipe 4' above surface.

1 <i>s</i> .	I hereby ertify that the foregoi	ing true and correct		
	SIGNED RIMINA	Jones	Production Superintendent	3-19-74
÷				DATE
	(This space for Federal or Atate	office use)		
	TREPAYED BY	(army p		

PUTITIO DIEL

DATE

*See Instructions on Reverse Side