

- 2-23 CORRAL DRAW UNIT #1
(54) 7492 drlg lm & sh, 12-1/4" hole, 1-1/2° at 7360 9.3# Br wtr
- 2-24 (55) 7902 drlg lm, 12-1/4" hole, NND 9.3# Br wtr
- 2-25 (56) 8210 drlg lm, 12-1/4" hole, 1/2° 7950 9.3# Br wtr
- 2-26 CORRAL DRAW UNIT #1
(57) 8426 drlg lm & sh, 12-1/4" hole NND. 9.5# Br wtr.
- 2-27 CORRAL DRAW UNIT #1
(58) 8469 ND lm & sh, 12-1/4" hole, 1/2° at 8469 9.5# Br wtr.
POH w/bit #3, ran bit #4, stuck at 8402', spot 125 bbls oil at bit,
let soak past 2-1/2 hrs.
- 2-28 CORRAL DRAW UNIT #1
(59) 8469 ND lm & sh, 12-1/4" hole NND 9.5# Br wtr
rig up Dia Log ran free point indicator bit & reamer stuck at 8402'
backed off at 8355' left bit reamer & 2 7" DC's in hole POH ran jars DC's
accelerator sub & DP to 8355' screwed into fish jarred fish loose
screwed into fish jarred fish loose w/1 jar circulated oil out of hole
POH rec fish now rerunning Bit #4.
- 3/1 CORRAL DRAW UT #1
(60) 8583 dlq lm & sh, 12 1/4" hole, NND, 9.5# Br wtr.
Bit #4 HTC J55R 114, 16 1/4 hrs. reamed 120' 4 1/2 hrs.
- 3-2 CORRAL DRAW UNIT #1
(61) 8820 drlg lm & sh, 12-1/4" hole, NND 9.5# Br wtr
- 3-3 (62) 9064 drlg lm & sh, 12-1/4" hole, NND 9.5# Br wtr
- 3-4 (63) 9186 ND lm, 12-1/4" hole, 1-1/4° at 9131 9.5# Br wtr
Down past 10 hrs for rig repair.
- 3/5 CORRAL DRAW UT #1
(64) 9186 ND lm, 12 1/4 hole, NND, 9.5# Br Wtr.
down past 24 hrs for rig rprs.
- 3/6 CORRAL DRAW UT #1
(65) 9370 drlg lm & sh, 12 1/4 hole, NND, 9.5# Br Wtr.
down add'l 3 1/4 hrs for rig rpr.
- 3/7 CORRAL DRAW UT #1
(66) 9635 drlg lm & sh, 12 1/4 hole, NND. 9.5# Br Wtr.
- 3/8 CORRAL DRAW UT #1
(67) 9765 drlg lm & sh, 12 1/4 hole, 1 1/4 @ 9650. 9.5# Br Wtr.
- 3/9 CORRAL DRAW UT #1
(68) 9995 drlg lm & sh, 12 1/4 hole, NND. 9.5# Br Wtr.
- 3/10 (69) 10,251 drlg lm, sh & sd, 12 1/4 hole, NND. 9.5# Br Wtr.
- 3/11 (70) 10,495 drlg lm & sh, 12 1/4 hole, NND. 9.5# Br Wtr.