

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-1-1-1-1

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole		6. LEASE DESIGNATION AND SERIAL NO. NM 0512668	
2. NAME OF OPERATOR Cities Service Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 4906 - Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FWL of Sec. 21-T25S-R24E, Eddy Co., N.Mex.		8. FARM OR LEASE NAME South Caverns Unit A	
14. PERMIT NO. 30-015-21077		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3795' GR.		10. FIELD AND POOL, OR WILDCAT UNDES., WASHINGTON RANCH MORROW	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21-T25S-R24E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting, and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

T.D. 7550' Shale. Plugged & abandoned. This well was drilled to a T.D. of 7550' and plugged & abandoned in the following manner:

- Set a 35 sx cement plug @ 7050'-6950' across top of Morrow @ 7006'.
- Set a 35 sx cement plug @ 6200'-6100' across top of Strawn @ 6152'.
- Set a 35 sx cement plug @ 5600'-5500' across top of Dean @ 5525'.
- Set a 60 sx cement plug @ 4300'-4200'.
- Set a 60 sx cement plug @ 3100'-3000'.
- Set a 60 sx cement plug @ 1900'-1800'.
- Set a 60 sx cement plug @ 1000'-900' (1/2 in and 1/2 out of 13-3/8" csg set & cemented @ 940').
- Set a 20 sx cement surface plug @ 30'-0' with a 4" Dry Hole Marker extending 4" above the ground to designate a plugged and abandoned location.
- This location will be cleared of all equipment and debris and your office will be notified for final inspection.

RECEIVED

RECEIVED

MAR 1 1974

FEB 24 1975

U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

U.S.G.
REGIONAL OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Region Oper. Mgr.

DATE March 27, 1974

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE
CONDITIONS OF APPROVAL, IF ANY:

DATE