

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-21-81
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-9681
7. Lease Name or Unit Agreement Name CHELSEI
8. Well No. 1
9. Pool name or Wildcat Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator H. E. LEE ✓	
3. Address of Operator 1306 Meadow Lane Roswell, New Mexico 88201	
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 2 Township 26 South Range 25 East NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Continuous Operations <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-11-91 thru 10-18-91

Drill out cement to 545'. Cleaned out to 560'.

10-19-91 thru 10-31-91

Clean out well from 560' to 595' and tag more cement. Drill out cement from 595' to 634'.

11-1-91 thru 11-7-91

Drill cement from 634' to 655'. Drilling very hard cement. Change bits and continue drilling cement.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. E. Gene LEE TITLE Owner DATE 11-9-91

TYPE OR PRINT NAME H. E. Gene LEE TELEPHONE NO. 622-7355

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE NOV 21 1991

CONDITIONS OF APPROVAL, IF ANY: