

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-03021
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2991
7. Lease Name or Unit Agreement Name  Milepost C
8. Well No. 1
9. Pool name or Wildcat Milepost Morrow

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3393 DF
2. Name of Operator JFG Enterprise	
3. Address of Operator P.O. Box 100, Artesia, NM 88210	
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>26S</u> Range <u>25E</u> NMPM <u>Eddy</u> County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- 12-1-94 Set CI Bridge Plug @ 10000'
  - 12-2-94 Ran Tubing, Circ. Mud, Spot 25 sx cement on CI Plug from 10000' - 9760'. Pull Tbg. to 7500'. Spot 25 sx from 7500' - 7260'. Pull Tbg. to 5250'. Spot 25 sx from 5250' - 5000'. Pull Tbg. Shut Down.
  - 12-3-94 Tag Cement @ 5000'. Freepoint 5-1/2" Casing @ 4800' Cut & Shut Down.
  - 12-5-94 Pull & Lay Down 5-1/2" Casing. Run Tbg. to 4850'. Spot 35 sx Cement 4850 - 4650'. Pull Tubing to 1800'. Shut Down.
  - 12-6-94 Spot 25 sx from 1800' - 1675'. Pull Tbg. to 60'. Circ. 15 sx to Surface cut off Wellhead. Install Marker, fill Pits, Rig Down. Move off. Class C Cement. Mud 25# per bbl. salt get.
  - 1-5-95 Cut anchors. Clean location. Stock tanks on location will be used as fresh water storage for Mary Foster (Foster Ranches) 314 Dell City, Tx. 79837, 915-964-2865 per authority of Tim Gumm, Supervisor OCD District II.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. T. Jackson TITLE Partner DATE 1-16-95

TYPE OR PRINT NAME J. T. Jackson TELEPHONE NO. 746-9680

(This space for State Use)

APPROVED BY Man Jimenez TITLE Field Rep DATE 7-17-95

CONDITIONS OF APPROVAL, IF ANY: