

CORRAL DRAW UT #2

- 1/4 (20) 2885 ND fishing, 12 $\frac{1}{4}$ hole, 9.7-39-25.0.
attempt to rel OS from fish @ 2454 w/ no success, RU Dia-Log, ran sinker bars to 2348, ran spud bars & SP, CO to 2353, unable to CO any deeper, Dia-Log truck broke down, WO truck 4 hrs, ran free pt indicator, fishing string stuck @ 400-450, prep to BO & WO.
- 1/5 (21) 2885 ND fishing, 12 $\frac{1}{4}$ hole, 9.7-44-0.
ran string shot, BO 5 $\frac{1}{2}$ DP @ 392, POH, ran crooked jt of DP, washed down beside fish from 392-600, POH, ran DP, screwed into fish @ 392, indicated fish stuck between 400-450, BO @ 392, POH, ran 8-3/4 OD x 7 $\frac{1}{2}$ ID WO shoe on 9 jts 8-1/8 WP, jars, DC's & DP, unable to get over fish, POH, ran 12" x 10" x 8 $\frac{1}{2}$ long WO mill on WP, jars, DC's & DP, WO fish from 392-649, circ & cond mud, prep to pull WP.
- 1/6 (22) 2885 ND fishing, 12 $\frac{1}{4}$ hole, 9.7-44-0.
POH w/ WP, ran DP, screwed into fish @ 392, BO DP @ 641, POH, ran WP, WO DP 641-896, POH w/ WP, ran DP, screwed into fish, BO DP @ 2321, circ 1 hr, POH, ran Dia-Log sub on DP, ran Dia-Log, CO pipe, CO inside of fish from 2321-2541, corrected top of OS, unable to CO thru OS, BO @ 2517, POH, changed out 5 DC's, rerun fishing string, screwed into fish @ 2517, prep to jar on fish.

CORRAL DRAW UT #2

- 1/7 (23) 2885 ND fishing, 12 $\frac{1}{4}$ " hole, 9.7-44-0.
jarred on fish 30 min, jars stopped working, BO fish @ 2517, POH, changed out jars, rerun to 2517, screwed into fish, jarred 30 min, DP parted @ 322, DP had been cut w/ mill, ran OS, caught fish, BO @ bottom of accelerator sub, POH, rerun fishing string, screwed on to bottom of accelerator sub, BO @ 2517, POH, checked fishing string, rerun fishing string w/ kick sub, attempted to screw into fish 3 $\frac{1}{2}$ hrs from 2500-2540, broke disk in kick sub, POH, rpr kick sub, now rerunning fishing string.

CORRAL DRAW UT #2

- 1/8 (24) 2885 ND fishing, 12 $\frac{1}{4}$ hole, 9.7-44-0.
finish running kick sub to 2517, unable to screw into fish, POH, rerun fishing string w/ knuckle jt, unable to screw into fish, POH, ran crooked jt of DP, attempted to find top of fish w/ no success, POH, ran 8-5/8 wallhook & OS on fishing string, attempted to catch fish w/ no success, POH, ran wallhook, OS & knuckle jt on fishing string, screwed into fish, jarred 5 times, RU Dia-Log, ran string shot on outside of DP & DC's stopped @ 2552, Dia-Log meas, prep to fish plug out of knuckle jt.

CORRAL DRAW UT #2

- 1/9 (25) 2885 ND fishing, 12 $\frac{1}{4}$ " hole, 9.7-44-0.
Dia-Log ran string shot, BO fish @ 2550, POH, rec 1 DC & 1 set Bowen jars, rerun fishing string, attempted to screw into fish @ 2550, top of fish either bad or crooked, unable to screw in, POH, rerun fishing string w/ 8-5/8 OS w/ 6"