GREAT ESTERN DRILLING COMPANY #1 HAY ... LLOW UNIT

Location: 2080' FSL & 1980' FEL Section 11, T-26-S, R-27-E, Eddy County, New Mexico

- 3-8-75 Day 58. TD 12,966' driller, 12,983' Schlumberger. Running logs on 1st run. Spent 6½ hrs circ for logs, 1½ hrs cleaning pits, 5½ hrs circ off gas, 1½ hrs spotting 12½# mud on bottom, 4½ hrs trip out, 4½ hrs logging.
- 3-9-75 Day 59. TD 12,966' driller, 12,983' Schlumberger. Circ & cond hole. Prep to spot 12# mud on bottom to run csg. Mud wt 10.7#, vis 41 to 42, WL 22, FC 2/32", PH 9. Spent 7 hrs logging & rigging down loggers, 6 hrs trip in hole, 11 hrs circulate gas off & cond mud. Ran compensated neutron formation density & caliper & dual laterallog-RXO logs. So fluid loss or gas last 6 hrs.
- 3-10-75 Day 60. TD 12,966' driller, 12,983' Schlumberger. PBTD 12,678'. Cementing first stage. Mud wt 19.7#, vis 42, NL 22, FC 2/32" PH 9. Ran 115 jts of 55" P-110 17# per ft. LT&C Republic, 84 jts of 5号" N-80 - 17# LT & C CF & I and 107 jts of 5号" N-80 17# Buttress youngstown w/2 Lynes ECP packers and Halliburton DV RECEIVED tool. A total of 306 [ts (12,662') were set @ 12,678'. Bottom Lynes ECP packer was set @ 9368'. Upper Lynes ECP packer was set @ 5924'. DV tool was set @ 9117'. Rough coated 7 its APR 1 0 1975 of casing as follows: 3 jts 12,422-12,546'; 2 jts 11,969-12,049'; 2 Jts 11,597-11,684'. Ran 10 centralizers over the above in-O. C. C. terval. Started cementing 1st stage preceded by 500 gal of mud ARTEBIA, OFFICE flush & followed by 710 sax Class "H" cement + 8# per sack of salt + 4/10 of 1% HR-4 retarder. 1 hr circ & cond mud, 2½ hrs spotting 12# mud on bottom, 7½ hrs LD DP & DC's, 4 hrs changing BOP rams & RU to run csg, 75 hrs running casing, 1 hr NO Halliburton & RU Halliburton to cement, 1/2 hr cementing.
  - 3-11-75 Day 61. PBTD 12,678'. WOC. Finished cementing 1st stage. PD @ 6:25 AM 3-10-75. Bumped plug w/3600# to set lower ECP pkr. Dropped D-V opening bomb & cemented 2nd stage w/455 sax Nowco lite wate cement + 10# per sack of gilsonite + ½# per sack of Flo-seal. PD 8 AM 3-10-75. Bumped plug w/4700# to set Lynes upper ECP pkr. Confirmed setting of upper ECP pkr by pressuring annulus between 8-5/8" & 5½" csg to 250#. Spent 1½ hrs pumping cement & displacing cement & setting ECPs, ½ hr wait on D-V bomb to fall, 22 hrs WCC. Now nippling. Ran temperature survey. Found top of 2nd stage cement outside (@ 6400'. Found cement invide csg @ 9080'. Set slips & cut off pipe. Left 130,000# on slips.
  - 3-12-75 Day 62. PBTD 12,678'. Circ. hole. Preparing to displace w/clean brine water. Spent 4 hrs nippling up, 4 hrs unload-ing tbg, tallying, removing protectors & preparing to run, 1 hr jet cellar & HU fresh water tanks, 1½ hrs drill cement & DV tool, ½ hr tstg DV tool to 1500#. Held OK, 13½ hrs PU DC & tbg & running in hole.

ILLEGIBLE

- 3-13-75 Day 63. PRTD 12,678'. Ran dement bond (4.4 tie in log. Found good demont opposite zones to be periorated. Now GFM w/tbg & Baker pkr. Spent 3/4 hr PM tbg, 3/4 hr drilling dement on top of float collar, 2½ hrs circulating & putting up tbg board, 1½ hrs displacing hole w/clean brine water, 6 hrs pulling tbg 5 ints, 9½ hrs RM loggers, logging & rig down loggers, 1 hr dressing pkr & GFM, 2½ hrs working on power tongs.
- 3-14-75 Day 64. Finished running tubing. Set pkr @ 12,110'(5½ X 2 Baker Lock-set) w/1.181 profile @ 12,103' & sliding sleeve @ 12,068'. Flanged up BOP. Fished blanking plug. Pressured tbg to 4000 PSL w/60,000 CFT. Held OK. Perf Morrow: 12,290-294; 12,439-445; 12,468-481; 12,503-510 w/2 JSPF w/ 1 11/16" hyperdome jet perforator (30' 60 holes .29" diam.) Opened well to flow. Unloaded nitrogen in 45" & died. Fluid level while fishing blanking plug was (\* 10,470'.
- 3-15-75 Day 65. Filled tbg w/water. Pressured tbg to 5500# & formation broke. Ran Nowsco tubing unit & displaced wtr down to pkr w/N2. Treated Morrow perfs w/3000 gal 75% MS acid w/1000 CFN2/bbl + 6000 CFN2 pad. Flushed w/33 bbls KCL wtr w/1000 CFN2/bbl. Used 100-7/8" balls in 4 stages. When 2nd stage ball on perfs press increased to 8400%. Pressure broke back to 6100%, then decreased to 5600# @ end of flush. ISIP 4000# 5" SIP 3950%. Total load 105 bbls. Max press 8400#. Ave IR 4.2 BPM. Job just now finished. Now nippling up tree & prep to flow.
  - 3-16-75 Day 66. SITP 1 hr & 20" after treatment was 3650#. Opened to pit, unloading load wtr and N<sub>2</sub>. FTP decreased to o# in 1 hr. Flowed an additional 1 hr by heads and died. Have recovered an estimated 50 BLW. RU Nowsco & ran Nowsco tbg to 12,040' unloading wtr from tbg. POOH & RD Nowsco. Started flowing gas @ est rate of 25 MCFGPD w/0# FTP. Rate remained steady throughout night.
  - 3-17-75 Day 67. SI @ 7:45 AM 3-16-75 for buildup. Surface TP 170#
    @ 8:45 AM, 205# @ 9 AM, 245# @ 9:15 AM, 280# @ 9:30 AM, 320#
    @ 9:45 AM, Opened to pit on 3/4" ck. Blew down in 6 min.
    Installed 2" orifice well tester on flow line w/4" plate.
    FARO 44 MCFGPD for 3 hrs. Decreased to 40 MCFGPD last ½ hr.
    Worked 18# mud in frac tank. Transferred 125 bbls to rig mud
    tanks & cut w/200 bbls fresh wtr. Mixed 75 sax gel & 5 sax
    of no-oxygen & 35 gal aquatech. Mud was 11.4#, vis 52, 50,000
    PPM chlorides. Ran Otts wireline & opened stiding sleeve
    above pkr. Displaced hole w/11.4# mud. Released rig @ 1:30
    AM MDST 3-17-75 Spent 2% hrs flowing well, 2 hrs w/well Sf, 6 hrs conditioning mud, 4 hrs w/Otts slick line, 5 hrs displaced for with mud.

**ILLECIBLE** 

-----