المسامة	کہ عدوراً	State of New Mexico		Santa Fe	ार्का:		
Submit 3 Copies to Appropriate	Er v, Minerals and N			LE ₁ le	100	Form C-103	
District Office	TO 1, IVERSELES MINE IA	A SECULIAR 1	caoutos Department	and Office	++-	Revised 1-1-89	
DISTRICT I	Off COMPEDI	7 A FEVE	ON DYTHOLON	B of M	TH		
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERV	A 1 10 Box 20		WELL APIN			
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210	Santa Fe, New M			30-0 5. Indicate 1	15-2149	7 	
DISTRICT III				J. IBLBCAR	ype or Lorens STA	TE 🔀 FEE 🗌	
1000 Rio Brazos Rd., Aztec, NM 8741				6. State Oil K-05	& Gas Leass No.		
	OTICES AND REPORTS C						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name			
1. Type of Well:			ECEIVED	-			
OL X GAS WELL	OTHER			ББОТ	2 State	_	
2. Name of Operator			UIII 0 = 100	& Well No.	2 State		
Texaco Producing	Inc.V	·	10N ()8 '89	1			
3. Address of Operator				9. Pool name	or Wilder	,	
PO Box 728, Hobb	os, NM 88240		G. C. D.	Unde	S. LORY	Delaware	
	0.00		WESHA, OPPICE				
Unit Letter:	980 Feet From The NOT	rth	Line and19	80 Foot	From The	West Lime	
2	m 11 340	_	215	_			
Section 2	Township 24S	Ri	inge $31\mathrm{E}$) DF, RKB, RT, GR, etc.)	NMPM	Eddy	County	
	3475' GR		or , row, ar, on, ac.,				
11. Check	k Appropriate Box to Ind		Nature of Notice De				
	NTENTION TO:	ncau.		-	ner Data FREPORT	OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING	CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	OPNS.	PLUG AND	ABANDONMENT [
PULL OR ALTER CASING			CASING TEST AND CE	WENT IOR	1		
					J		
OTHER:		. 📙	OTHER: Pluq	back		[x]	
12. Describe Proposed or Completed Ope	erations (Clearly state all pertinent d	letails, an	d give pertinent dates, includ-	ine estimated da	to of starting and		
work) SEE RULE 1103.				-d comment on	ic of sectors ext	proposes	
	_						
1) MIRU. Pull r	ods and pump. I	nsta	11 BOP. Pull	l tubing	·		
2) GIH with 7 5/	8" CIBP and set	at 1	0,795' Cap	with 35	cemen	t.	
3) GIH with secon	nd 7 5/8" CIBP a	nd s	et at 8035'.	Cap wi	th 35'	cement.	
New PBTD at 8		7017	1 -1 2 CDE /C		. 7		
4) Perf Delaware5) Acidize perfs	interval 7210'-	721/	Tat 2 SPF (8	3; 16 h	ores).	3	
6) Swab test 5 h							
7) Fracture treat with 20,000 gallons gelled 2% KCL and 30,000 lbs.							
	ut-in.	T T O 11	a Action 70 L	CD alla	JU, UUU	D. + T.	
	uction equipment	_				Post I. 6-16.	
	tential ending 1		AM. 6/4/89	Plimped	75 BO		
	227. Grav-38.8		, 0/ 3/ 0/ 1	r mubed	. , , , , , ,	H-7 A	
		- •					
I hereby certify that the information above is tr	ye and complete to the best of my knowle	odge and b	397-3571				
1 . //	, , , , , , , , , , , , , , , , , , , ,	•					

I hereby certify that the information above is true-and complete to the best of my knowledge and balled.

397-3571

SKONATURE Jakea Superintendent 6/6/89

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY MIKE WILLIAMS

JUN 1 4 1989

SUPERVISOR, DISTRICT

CONDITIONS OF APPROVAL, IF ANY: