

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

COPY TO: (Other, distinct, or reverse side)

COPY TO: (Other, distinct, or reverse side)
Budget Bureau No. 42 R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRY HOLE		5. LEASE DESIGNATION AND SERIAL NO. NM 20949	
2. NAME OF OPERATOR GREAT WESTERN DRILLING COMPANY		7. UNIT AGREEMENT NAME HAY HOLLOW UNIT	
3. ADDRESS OF OPERATOR BOX 1659, MIDLAND TX 79701		8. FARM OR LEASE NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter F, 1980'FNL 1980'FWL, Sec. 12, T-26-S, R-27-E		9. WELL NO. 2	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT WILDCAT	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3176.1 GR		11. SEC., T., R., M., OR BLK. AND SURVEY OR ABQA SEC. 12, T-26-S, R-27-E UNIT LETTER F	
		12. COUNTY OR PARISH EDDY	
		13. STATE NEW MEXICO	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/6/75 thru 8/19/75: Drilled 6½" hole from 9401' to 13,121' T.D.

8/19/75 Abandonment procedure was verbally approved by USGS representative Mr. Jim Knauf.

8/20/75 Set plugs as follows: 50 sx Class "H" cement @ 12,300'-12,500', 100 sx 11,440'-11,840'. Set BP @ 9360' w/15 sx cmt on top, 9310'-9360'. Used mud laden fluid between all plugs.

8/21/75 Cut 7-5/8" Csg. @ 5829'. Rec. 5,809' of 7-5/8" Csg.(139 jts). Set 60 sx plug 5754'-5904', 50 sx 4100'-4200' & 65 sx 2280'-2380'. Cut off wellhead.

8/28/75 Fluid in 10-3/4" csg, dead. No bubbles. Set 15 sx plug (20') at surface with dry hole marker.

NOTICE will be given when final cleanup has been made and location is ready for final inspection.

RECEIVED

MAR 10 1976

U. S. G. S.
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

General Superintendent

DATE

8-29-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side