

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug wells. Use the APPLICATION FOR PERMIT to Drill or Deepen or Plug Wells.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRY HOLE
MAY 31 1979

2. NAME OF OPERATOR
GREAT WESTERN DRILLING COMPANY

3. ADDRESS OF OPERATOR
BOX 1659, MIDLAND TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

Unit Letter F, 1980'FNL 1980'FWL, Sec. 12, T-26-S, R-27-E

14. PERMIT NO. 30-215-21549
15. ELEVATIONS (Show whether DE, RT, GR, etc.)
3176.1 GR

7. UNIT AGREEMENT NAME
HAY HOLLOW UNIT
8. FARM OR LEASE NAME

9. WELL NO.
2
10. FIELD AND POOL, OR WILDCAT
WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
SEC. 12, T-26-S, R-27-E
UNIT LETTER F

12. COUNTY OR PARISH
EDDY
13. STATE
NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	WELL OR WELL CLOSING
FRACURE TREAT	WELLHEAD COMPLETE
SHOOT OR CHARGE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACURE TREATMENT	ALTERING CASING
SHOOTING OR CHARGING	ABANDONMENT*
(Other)	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

17. DESCRIBE PROPOSED OR COMPLETED WORK, including all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

7/6/75 thru 8/19/75: Drilled 6 1/2" hole from 9401' to 13,121' T.D.
8/19/75 Abandonment procedure was verbally approved by USGS representative Mr. Jim Knauf.
8/20/75 Set plugs as follows: 50 sx Class "H" cement @ 12,300'-12,500', 100 sx 11,440'-11,840'. Set BP @ 9360' w/15 sx cmt on top, 9310'-9360'. Used mud laden fluid between all plugs.
8/21/75 Cut 7-5/8" Csg. @ 5829'. Rec. 5,809' of 7-5/8" Csg. (139 jts). Set 60 sx plug 5754'-5904', 50 sx 4100'-4200' & 65 sx 2280'-2380'. Cut off wellhead.
8/28/75 Fluid in 10-3/4" csg, dead. No bubbles. Set 15 sx plug (20') at surface with dry hole marker.

NOTICE will be given when final cleanup has been made and location is ready for final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED: *A. D. Dill*

TITLE: General Superintendent

DATE: 8-29-75

(This space for Federal or State office use)

APPROVED BY: *Joe J. Lara*
CONDITIONS OF APPROVAL, IF ANY:

TITLE:

DATE: MAY 12 1979