

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

CLSF

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other		5. Lease Serial No. NM 17574
2. Name of Operator BILL & PATSY RICH		6. If Indian, Allottee or Tribe Name
3a. Address 2401 MARTIN LANE	3b. Phone No. (include area code) (505) 889-3928	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SEC 11, T-25S, R-24E 660 FEL + 1980 FSL		8. Well Name and No. FABRON Federal #1
		9. API Well No. 2-015-21913
		10. Field and Pool, or Exploratory Area
		11. County or Parish, State Eddy

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See Attached

RECEIVED
FEB 22 AM 10 43
BUREAU OF LAND MANAGEMENT
CATTLEHEAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Bill Rich

Title *Owner*

Signature *Bill Rich*

Date *2/22/02*

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by
Conditions o
certify that t
which would

Accepted for record

only

FEB 22 2002

Title

Date *2/25/2002*

Office *CFC*

Crime for any person knowingly and willfully to make to any department or agency of the United
ny matter within its jurisdiction.

Bill & Patsy Rich

Taskin Federal #1

Sec. 11, T-25S, R-24E

460 FEL + 1980 FSL

Eddy County, NM

P+A Procedure

1. RUPU, POOH w/ rods & pump lay down rods
2. NUBOP & POOH w/ Tbg, RU Wireline & set CIP
@ 1900' CAPW/35' CMT
3. NUBOP & Free point 4 1/2" CSG, CUT CSG 50'
Above Free point
4. POOH w/ 4 1/2" CSG + Lay down
5. TIT w/ Tbg & Circ hole w/ 10# brine salt gel
6. Set 255x CMT plug 50' above & below 4 1/2" STAB
7. Set 255x CMT plug @ 8 5/8" shoe 50' above & below
289' TO 189'
8. CUT off well head & set 105x surface plug
w/ 4" P+A Marker 4' above ground level w/
Well information welded on Marker including
P+A Date
9. Clean location rim & seed w/ required
seed

Ashcroft Pad
 Sec 11, T-25S, R-24E
 660' FLL + 1980 FSL
 Eddy County, NM

Proposed PTH

10" x 30" Surface
 Plug

60' minimum

wood tag plug

255X STUB PLUG
 50' ABOVE + BELOW
 STUB 289' TO 189'

12 1/4" hole
 8 5/8" 32# @ 239' INT CIR

255X CMT PLUG
 50' ABOVE + BELOW
 STUB

wood tag plug

← TOC @ 1674' b/c CBL

CIBP SET @ 1900
 44A 10/20/2000

= Formations
 = 1717' TO 1935'
 = 1935' TO 2032'
 = 77.2 hole
 > 4 1/2" 11.6# CMT w/ 255' LWT
 TOC @ 1674' b/c CBL