

P. O. BOX 2267, MIDLAND, TEXAS 79701 (915) 603-487

· 1221731. -333 - 237 وه المحمد ال المحمد المحمد

4.

November 30, 1977

New Mexico Oil Conservation Commission D. S. Nurver, Chief Engineer P. 0. Eox 2058 State Land Office Building Santa Fe, New Mexico 87501

> RE: Exception Rule 107 Tubing Requirements Sub-Paragraph 3 - Setting Depth HNG - Grynberg Fed. Com. 11 #1 Eddy County Sec. 11, TWP - 25S, Rge-28E

Gentlemen:

In the subject completion the casing program utilized a liner arrangement to serve as the production casing string. In conjunction with this, a P.B.R. (polished bore receptacle) and seal assembly was installed at the top of the liner in lieu of a conventional type packer. This arrangement allows us to have a high burst string of intermediate casing in place before drilling into possible high pressure zones. We felt this type of casing program is not only safer, but also will allow more flexibility in plugging back from the Morrow to the Atoka Zone.

Completing this well in this manner resulted in the bottom of the tubing terminating at the top of the liner. Therefore, an exception to Rule 107 is requested.

Yours very truly,

MNG 011 Company and an an and a second

Salla Roach

cc: H. C. Livingston Well File

Mr. Bill Gressett N.M.O.C.C. Artesia, New Mexico

OR/mc