## 

Form 9-331 Dec. 1973	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	<u>NM-22628</u>
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	•
SUNDRY NOTICES AND REPORTS ENCLOSE (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
1. oil gas well well other OCT 2 5 1978	Scheidt Federal
2. NAME OF OPERATOR	9. WELL NO.
Exxon Corporation / O.C.C.	<u>1</u>
3. ADDRESS OF OPERATOR	
	Wildcat
P. O. Box 1600, Midland, Texas 79702	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: 1880' FSL & 825' FWL	Sec. 30, T-26S, R-26E
AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Eddy New Mexico
	14. API NO.
16. CHECK APPROPRIATE BUX TO INDICATE NATURE OF NOTICE,	<u>30-015-22</u> 460
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	Later
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	Jacel
TEST WATER SHUT OFF	이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이
FRACTURE TREAT	Mobile Motion And And And And And And And And And And
	(1) 10 10 10 10 10 10 10 10 10 10 10 10 10
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	change on Form 9–330.)
	· · · · · · · · · · · · · · · · · · ·
ABANDON*	
(other) Sidetrack Hole	
	이 아프 정말 것 않았는 것 것 않았다.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date cf starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent	t to this work.)*
9-17-78 - Lost returns while drilling at 11,45	15' and gas came in from
GOOVE, III ALL ALL ALL ALL ALL ALL ALL ALL ALL	
stabilizer, nineteen 7" drill collars for a to	tal of (171, short drill collar,
10-9-78 - Set cement plug from 10,600'-10,828'	was left in the hole.
with 0.75% FR2 $\frac{1}{24}$ Flocelo $\frac{34}{100}$ Cilconite and	with 150 sacks Class H cement
with 0.75% FR2, $\frac{1}{2}$ # Flocele, 3# Gilsonite per s ft. per sack.	ack. Slurry 16#per gallon, 1.2 c
ic, per sack.	
10-13-78 - Set cement plug 10,150'-10,642' wit	:h 324 sacks Class H with 10∦
10.5 Danu per Sack, $16$ Grk Z, $1/10$ of $12$ Hg7	Top of pluce found on 10 00/1
TO 19 TO - After dressing off plug to 10.360	a dynadrill with bont out and
run to sidetrack the junk in hole. Now drilli	ng sidetracked hole.
	and the second
<pre>cc: Offset Operators - (See Attachment)</pre>	905,005 905

Subsurface Safety Valve: Manu. and Type \_ e: Manu. and Type \_\_\_\_\_\_ Set @\_\_\_\_\_\_ t the foregoing is true and correct \_\_\_\_\_\_ Ampling\_\_\_\_\_\_TITLE Proration Specialistre \_\_\_October 17, 1978 Ft. 18. I hereby certify that the foregoing is true and correct SIGNED TILLA Whis space for Federal or State office use) OCT 2 4 1978 APPROVED BY CALL TITACTING DISTRICT ENGINEER COUTRACT COUTRACT COURS LAL ATAC ALUTA HEAL ALUTA e most 10 most

\*See Instructions on Reverse Side

.