

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 0438001

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Texas Pacific Oil Company Inc.

3. ADDRESS OF OPERATOR

1700 One Main Place Dallas, Texas 75250

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

Unit L 1980 'FSL &amp; 660' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Phantom Draw 11.

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Phantom Draw 1101/222 p

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 30, T265, R31E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR 3076'; KB 3095'

RECEIVED

JUN 14 1978

D.C.C.

ARTESIA, OFFICE

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5/26/78 Lost 13 jts. of 8 5/8" casing in 11" hole after hitting bridge @ 3710' while running intermediate casing. (Casing parted @ 3161' leaving 8 5/8" csg. from 3161 to 3710')

5/26/78 Attempted to retrieve casing with drill pipe and fishing tools; attempts to were unsuccessful.

5/28/78 Spotted two cement plugs in open hole: Plug #1 3161' to 3000'  
Plug #2 3000' to 2505'

5/29/78 W.O.C. for plugs to set.

5/30/78 Drld. cmt to 2682'; ran 2 1/2" Bent sub and sidetracked 11" hole around lost 8 5/8" casing.

Deviations after side tracking 3 1/4" @ 2830'; 3" @ 2950'; 3 3/4" @ 3140'

RECEIVED

JUN 8 1978

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Dr. Admin. Supt.

DATE

6/5/78

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE

JUN 12 1978

CONDITIONS OF APPROVAL, IF ANY: