

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

USA-NM-19423

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

Coyote - Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

34-25S-26E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug a well for a new use. Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

FEB 4 1980

2. NAME OF OPERATOR

Ford Chapman & Associates

3. ADDRESS OF OPERATOR

P. O. Box 2376, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirement. See also space 17 below.)
At surface

660' FNL & 660' FEL of Sec.

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED

FEB 27 1980

14. PERMIT NO.

32-015-23096

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3346.8 GL

ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐SHOOT OR ACIDIZE ☐ABANDON* ☒REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOTING OR ACIDIZING ☐ABANDONMENT* ☒(Other) Surface Casing ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Well was spudded on 1-10-80. On 1-12-80, 10 3/4" casing was cemented at 159' with 50 sacks of cement. 10" hole was drilled to depth of 650'. 8" hole was drilled to total depth of 2018'. Only fluid encountered in hole was 1/2 GOPH plus 14 GWPH from Delaware Sand.

Intend to abandon well as follows:

1. Load hole with mud (25# gel/bbl of water)
2. Spot 35-sack cement plug at TD.
3. Spot 35-sack cement plug at 1150'.
4. Spot 50-sack cement plug at 200'.
5. Spot 20-foot cement plug at surface.
6. Install 4" regulation marker inscribed as follows:

Ford Chapman
#1 Coyote - Fed.
660 FNL & 660 FEL
34-25S-26E

Plugging program orally approved by Ray Stall to Jim Knauf on 2-1-80.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 2-4-80

(This space for Federal or State office use)

APPROVED BY

GEORGE H. STEWART

TITLE

DATE

FEB 27 1980

CONDITIONS OF APPROVAL, IF ANY: