

EXHIBIT "H"

Partial List Of Auxiliary Equipment Follows:

1. Kelly cock
2. Flow show indicator
3. Pit level indicator
4. Full opening valve on floor for drill pipe
being used (inside POP)
5. Gas detector
6. Geolograph
7. Mud logger on location
8. Mud-gas separator
9. De-gasser
10. De-sander
11. De-silter