

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☐ well other P&A
2. NAME OF OPERATOR
The Superior Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 3901, Midland, Texas 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FEL, 1980' FSL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	☐	☐
FRACTURE TREAT	☐	☐
SHOOT OR ACIDIZE	☐	☐
REPAIR WELL	☐	☐
PULL OR ALTER CASING	☐	☐
MULTIPLE COMPLETE	☐	☐
CHANGE ZONES	☐	☐
ABANDON*	☐	☐

(other) P&A after testing Morrow & Bone Spring

5. LEASE
NM-16085
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Meander Federal "11"
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Wildcat
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
Section 11, T25S, R25E
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3460' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-15-83 MI RU PU.
6-16-83 Bled well, circ hole w/10# abandonment mud. WIH w/CIBP.
6-17-83 Set CIBP @ 6632', spotted 9 sx cmt on top BP. PBTD 6597', tested CIBP to 600 psi-0.K.
6-18-83 thru
6-22-83 Equip. broke. WO parts to repair.
6-23-83 WIH w/csg cutter, cut csg @ 4518', POH w/105 jts 7 5/8" csg. + 2 cut jts. (4508').
6-24-83 WIH, circ hole w/10# BW w/25#/bbl GE, spotted 100' (50sx) cmt from 4558-4458', RD, PCH. WOC.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ (Over) Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED G. E. Tate TITLE Div. Opr. Supt. DATE 7-6-83

APPROVED BY Peter W. Chester (Leave space for Federal or State office use)

APPROVED BY Peter W. Chester TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FEB 14 1984

*See Instructions on Reverse Side

ROSWELL, NEW MEXICO

Post ID-2
12-4-83
P&A

RECEIVED

JUL 2 14 PM '83
BUREAU OF LAND MANAGEMENT
ROSWELL DISTRICTRECEIVED BY
JAN 16 1984
O. C. D.
ARTESIA, OFFICE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

QTO : 1981 0 - 347-166

6-25-83 MIH, tagged cmt @ 4450', POH, MIH, spotted 75 sx Class H cmt plug from 1577' up, WOC.

6-26-83 MIH, tagged TOC @ 1454', spotted 77 sx cmt plug from 1030' to 930', WOC. Tagged cmt @ 908', from 1030' to 930', WOC. Tagged cmt @ 908', cut off Bradenhead, cleaned cmt from same, welded on dry hole marked, welded 2" 2MWP ball valve in dry hole marker plate.

6-27-83 SD operations. Will clean up location and remove production equipment. Final Report.

6-3-83

thru

6-27-83

6-26-83

6-25-83