

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND

(Do not use this form for proposals to drill or deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

AUG 20 1982

2. NAME OF OPERATOR

The Superior Oil Company OIL & GAS
MINERALS MGMT. SERVICE

3. ADDRESS OF OPERATOR

ROSWELL, NEW MEXICO

P. O. Box 3901, Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FNL, 1980' FWL of Sec. 12

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Strawn Recompletion Attempts.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Loaded well w/4% KCl wtr., SI.

2. Set Posi-plug @ 14,124', dumped 35' cmt on top of plug. POH.

3. Top of plug @ 14,117', dump bailed 14' cmt on top, RD. SIFN.

4. WOC 24 hrs.

5. Tested plug to 5000 # psi for 15 min. OK. Started swabbing, RD wireline, SIFN.

6. RIH w/2" perf gun 0° phasing. Tagged PBTD @ 14,100'. Perfd @ 13,774'-13,788' w/2. JSPF. POH.

7. RIH w/2" perf gun and perfd @ 13,740'-13,762' w/2 JSPF w/0° phasing. POH.

8. Jetted well w/N2, recovered 66 BW, jetted dry @ 13,500', POH.

9. Acidized well w/3,500 gals 7% acid, 2 g PT non-ionic surfactant, 2 g PT Clay-Stay, 100 g PT EGMBE, 10 g PT iron chelating agent, 85 ball sealers and 700 SCF N2/bbl.

10. Recovered acid load.

Subsurface Safety Valve: Manu. and Type

Set @ (over) Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

G. E. Tate

TITLE Prod. Supt.

DATE 8-13-82

G. E. Tate

(This space for Federal or State office use)

APPROVED (Orig. Sgd.) PETER W. CHESTER TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1981 0 - 347-156

11. Flowed well on 10/64" choke, SIFN.
12. Jetted well dry - recovered no fluid, jetted w/N2 - no fluid entry, repeated, POH, RD Cudd coil tbg unit.
13. Well SI for evaluation. Will attempt Bone Spring completion.