| Image: Santa FE, NEW MEXICO 87501 Sunta FE, New MEXICO 87501 | ENTIGY AND MINERALS DEPARTMEN | | | | | |
|--|--|---|---|--|-------------------|------------|
| Distribution P. 0. HOX 2088 Revised 10-1: Image: Art C SANTA FE, NEW MEXICO 87501 Suitable Control 10-1: Use: Since Cit Art Control 10-1: SANTA FE, NEW MEXICO 87501 Suitable Control 10-1: Use: Since Cit Art Control 10-1: SUNDRY NOTICES AND REPORTS ON WELLS Suite Cit Art Control 10-1: Understand SUNDRY NOTICES AND REPORTS ON WELLS Suite Cit Art Control 10-1: Understand Sunder Control 10-1: To Control 10-1: Inderstand Control 10-1: Sunder Control 10-1: Suite Cit Art Control 10-1: Inderstand Control 10-1: Suite Cit Art Control 10-1: Suite Cit Art Control 10-1: Inderstand Control 10-1: Suite 906 Blanks Building, Midland, Texas 79701 10. Field and Pool, of Widdeel Viet Control 10-1: Suite 906 Blanks Building, Midland, Texas 79701 10. Field and Pool, of Widdeel Viet Control 20-2: Suite 906 Slanks Building, Midland, Texas 79701 11. State Control 10-1: Intermition of Will Intermition of Shall work there DEF, RT, GR, etc.) 11. State Control 10-1: Intermition of Shall work Control 20-1: State 28E Notice Control 20-1: Intermition of Control 10-1: State 28E Notice Control 20-1: Intermition State Control 20-1: | | OIL CONSERVA | TION DIVIS' N | Fame: 6 103 | | |
| Image: Subject of the second secon | DISTRIBUTION | P. O. BO) | X 2088 " | Revised 10-1- | | |
| U.L.O.A. U.L.O.A. U.L.L | SANTA FE | SANTA FE, NEW | MEXICO 87501 | | | |
| i.t.mo office j.t.moser No. i.t.moser use the provide control of the office office of the office office of the office office of the office office office of the office | FILE 1 2 | | | Sa. Indicate Type of Lesse | | |
| OPERATOR S. SIME OIL & Gus Lusse No. Image: Subprovement of the second of th | U.S.O.S. | | | State X Fre | | |
| L-7017 SUNDRY NOTICES AND REPORTS ON WELLS Individual of the difference of | LAND OFFICE | | | 5. State Oil & Gus Lease No. | | |
| 100 act us this provide the provide the second active of a burden active act | OPERATOR | | | | | |
| It It <td< td=""><td></td><td>NOTICES AND REPORTS ON</td><td>WELLS ACA TO A DIFFENENT RESERVOIR. M PROPOSALS.]</td><td></td></td<> | | NOTICES AND REPORTS ON | WELLS ACA TO A DIFFENENT RESERVOIR. M PROPOSALS.] | | | |
| Hidde of Uperator 0. Form or Leose Hame Maddox Energy Corporation / Flower Draw 2 State J. Address of Operator 9. Well No. Suite 906 Blanks Building, Midland, Texas 79701 1 1. Location of Well 9. Well No. Unit certer G 1980 recert from the grade of Well 10. Field and Pool, or Widded Wildcat Wildcat The grade of the section 2 To anship 265 Hance 28E Inte grade 12. County 12. County 12. County 14. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent REPORT OF: PLUC AND ADANDON PLUC AND ADANDON PULL OR ALTER CASING PLUC AND ADANDON PULL OR ALTER CASING PLUC AND ADANDON OTHER Plug back, perf and test Atoka | | 07468. | | 7, Unit Agreement Nume | | |
| Maddox Energy Corporation / Flower Draw 2 State 1. Address of Operator 9. Well No. Suite 906 Blanks Building, Midland, Texas 79701 1 1. Contion of Well 10. Field and Pool, or Wildcat whit certes G 1980 the | | | | 8. Farm or Lease Name | | |
| 1. Address of Operator 9, Well No. Suite 906 Blanks Building, Midland, Texas 79701 1 1. defition of Well 10. Field and Pool, or Wildcat Unit Letter G 1980 THE Cast 1980 THE Cast 2 THE 265 HANGE THE 28E THE 28E THE 28E THE 2956' GL Eddy 12. County 2956' GL Eddy ThE PLUG AND ADANDON PLUG AND ADANDON PLUG AND ADANDON PULL OR ALTER CASING CHANGE PLANS OTHER PLUG BACk, perf and test Atoka | | poration / | | Flower Draw 2 State | | |
| Suite 906 Blanks Building, Midland, Texas 79701 1 4. Location of Well 10. Field and Poel, or Wildcal Unit certer G 1980 re G 1980 re east 10. Field and Poel, or Wildcal Via certer Mildcat via certer 1980 re east cine 2 via non the 1980 via certer 265 nee 28E nee 28E nee 2956' GL Eddy 2956' GL Eddy 2956' GL etady Plue and adandon notice of intention for Subsequent report of Other Data notice of intention for Plue and adandon remediat work Altering casing remediate casing Plue and adandon remediate casing Plue and adandon remediate casing Other Plans other Plug back, perf and test Atoka | | | | | | |
| 1. OCCHION of Well 10. Field and Pool, or Wildcal UNIT LETTER G 1980 FEET FROM THENOTTHENOTTHENOTTHE1980 VIldcat THE GAST 2 TO ANSHIP 26S NAMER Wildcat THE GAST 2 TO ANSHIP 26S NAMER 28E NMPM THE GAST 2 TO ANSHIP 26S NAMER 28E NMPM 10. Field and Pool, or Wildcat 1980 FEET FROM Wildcat Wildcat THE GAST 2 TO ANSHIP 26S NAMER 28E NMPM 10. Field and Pool, or Wildcat 1980 FEET FROM Wildcat Wildcat THE GAST 2 TO ANSHIP 26S NAMER 12. County 10. Field and Pool, or Wildcat 15. Elevation (Show whether UF, RT, GR, etc.) 12. County 2956' GL Eddy 10. Field and REM-DIAL WORK Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: FLUG AND ABANDON PLUC AND ABANDON Chance plans Commence Dritting Ophs. | | Building, Midland, Texas | \$ 79701 | 1 | | |
| UNIT LETTER G 1980 reet from thenorthline and1980 Wildcat The Eastline, section 2 T(anship 26S nance 28E NMPM. The Eastline, section 2 T(anship 26S nance 28E NMPM. The Eastline, section 2 T(anship 26S nance 28E NMPM. The Eastline, section 2 T(anship 26S nance 28E NMPM. The Eastline 2 T(anship 26S nance 28E NMPM. The Eastline 15. Elevation (Show whether UF, RT, GR, etc.) 12. County 12. County 2956' GL Eddy 2956' GL Eddy Township Plue and abandon Plue and abandon <t< td=""><td></td><td></td><td></td><td>10, Field and Pool, or Wildcat</td></t<> | | | | 10, Field and Pool, or Wildcat | | |
| UNIT LETTER G 1980 FEET FROM THENOFTHE | | | | Wildcat | | |
| 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ADANDON PLUG AND ADANDON PULL OR ALTER CASING CHANGE PLANS OTHER | UNIT LETTER G | 980 reet from the north | LINE AND 1980 FEET PHON | mmmmm [*] | | |
| 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ADANOON Remedial work ALTERING CASING PLUG AND ADANOON PULL OR ALTER CASING CHANGE PLANS OTHER OTHER | | | | | | |
| 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PIAFORM REMIDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON PLUG AND ABANDON PULL OR ALTER CASING CHANGE PLANS OTHER PLUG Back, perf and test Atoka | THE EAST LINE, SECTION | 2 TOWNSHIP 26 | <u>S</u> | | | |
| 16. 2956' GL Eddy Id. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDON PLUG AND ABANDON PLUG AND ABANDON NOTHER ALTERING CASING PLUG AND ABANDON OTHER <td <="" colspan="2" td=""><td>THIMMENT IN THE</td><td>15. Elevation (Show whether</td><td>DF, RT, GR, etc.)</td><td>12. County</td></td> | <td>THIMMENT IN THE</td> <td>15. Elevation (Show whether</td> <td>DF, RT, GR, etc.)</td> <td>12. County</td> | | THIMMENT IN THE | 15. Elevation (Show whether | DF, RT, GR, etc.) | 12. County |
| 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ADANDON REMEDIAL WORK ALTERING CASING PLUG AND ADANDON REMEDIAL WORK ALTERING CASING TEMPOBARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ADANDONMENT PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JGB OTHER_PLUG Back, perf and test Atoka | AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA | | | Eddy | | |
| NOTICE OF INTENTION TO: PLUG AND ADANDON PLUG AND ADANDON REMEDIAL WORK ALTERING CASING PLUG AND ADANDONMENT COMMENCE DFILLING OPNS. PLUG AND ADANDONMENT CASING TEST AND CEMENT JQB OTHER PLUG BACK, perf and test Atoka | | | | 5 | | |
| P' AFORM REMODIAL WORK ALTERING CASING PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PLUG AND ABANDON PLUG AND ABANDON PLUG AND ABANDONMENT COMMENCE DFILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JQB OTHER PLUG Back, perf and test Atoka | | | - | | | |
| Prevention Proce ARD ADADON Interce domain Plug and Adandonment TEMPORARILY ABANDON Change plans Commence of illing opns. Plug and Adandonment Pull of Alter casing Change plans Casing test and cement job Other Other Plug back, perf and test Atoka Commence of illing | NOTICE OF IN | ENTION TO: | | | | |
| TEMPORARILY ABANDON TEMPORARILY ABANDON TULL OR ALTER CASING CHANGE PLANS CHANGE PL | | PLUS AND AMANDON | REMEDIAL WORK | ALTERING CASING | | |
| PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COTHER_Plug back, perf and test Atoka | E E E E E E E E E E E E E E E E E E E | | i i i i i i i i i i i i i i i i i i i | PLUG AND ADANDONMENT | | |
| OTHER_Plug back, perf and test Atoka | 75 | | | | | |
| OTHER | PULL ON ALTER CASING | CHANGE PLANS | | and test Atoka | | |
| | | ا ئىسا | oner 1146 backs pert | | | |
| | OTHER | | | | | |
| 17. Descripe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propos | 17 Describe Proposed or Completed One | rations (Clearly state all pertinent detc | ails, and give pertinent dates, including | estimated date of starting any proposi | | |

See attached drilling report.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| ·ICHED Gudra D. Cary | nutOperations_Manager | DATE _ | June 1 | 30, | 1981 |
|--------------------------|-----------------------------|--------|--------|-----|------|
| ATTONIO AT Make Williams | TITLE OIL AND GAS INSPECTOR | DATE _ | JUL | 6 | 1981 |

.

CONDITIONS OF APPROVAL, IF ANY

DAILY DRILLING REPORT (Cont'd)

•

•

Yage _____

| FIELD | Wildca | t | COUNTY Eddy | | |
|-----------------------|--------------------------|-------------|--|--|--|
| TD 13450' PBTD 12845' | | | | | |
| Date | Depth | Days | Remarks | | |
| 6/18/81 | 13450' TD 12845' PBTD | 119 | P/Perf. PU Baker 7" lockset packer w/seating nipple on top. TIH on 406 joints 2 7/8" 6.50# N80 Rn8 tbg to 12623'. RU Dowell and spot 900 gal. 15% NE acid 12623-12100' w/10# 2% KCl water. Pulled and laid down 20 joints (618') tubing. ND 5000# BOP's. Set packer at 12012' w/11000# compression. String weight 72000#. NU 11" x 10000# Xmas tree. By WKM tested tree to 7500# - okay. Closed well in and shut down for nite. Prep to perforate 7" casing. | | |
| 6/19/81 | 11 | 120 | Perforating 7" casing. RU Schlumberger and 5000# grease lubricator. TIH w/2 1/8" Selectfire gun. Shorted out. TOH, found bottom 2 guns shorted. Left those guns out and TIH. Perf w/2 SPF At 12776', 12747 12696', and 1 SPF @ 12618', 12604', 12576', 12568', 12415', 12412', and 12332'. Top 2 guns did not fire. Hot shot more guns to location from Hobbs, NM. Guns shorted out. TOH, closed well in and shut down for nite. Prep to perf top 4 holes and treat by Dowell. | | |
| 6/20/81 | 11 | 121 | RU Schlumberger & perf 7" casing w/ 2 1/8" Selectfire gun @ 12152', 12169', 12189', 12265'. RD Schlumberger RU Dowell, broke down prfs w/previously spotted acid. Max. press on break down 5500#. Broke to 5300#. Acidized w/ 2000 gal. NE FE 15% acid and 34 ball seale w/good ball action. Inj. rate 6 BPM. Displaced w/ 10# 2% KCl water. All fluid nitrofied w/1000 SCF/bbl ISIP 4000#, 5" SIP 3810#, 10" SIP 3770#, 15" SIP 37509 After 1/2 hr TP 3600#. Open well to pits on 32/64" choke, press. to 0# in 1/2 hr. Rec. 65 bbl fluid w/ne gas. RU & swab, made 9 runs, GTS to burn on 3rd run, est. 10-15 MCF. Total load recovered 150 bbl. Closer well in & SD for nite. | | |
| 6/21/81 | | 122 | After SI 15 hrs TP 2900#, open on 32/64" choke to pit press to 0# in 1/4 hr. Rec. spray fluid, est GR 10-1 MCF. SI 2 1/4 hrs press. built to 200#. Opened to reserve pit, press. to 0# in 10 min., no fluid, GR Est. 10-15 MCF. Closed in and SD for nite. | | |
| 6/22/81 | H | 12 3 | SI for Sunday. After SI 24 hrs TP 3600#. Prep to blow down. | | |
| 6/23/81 | 11 , | 124 | After SI 42 1/2 hrs TP 4100#. Opened on 32/64" choke press. bled to 0# in 20 min. GR Est 1MM to 20MCF. RU & Swab, found fluid level at 3500', swbd to 10,200 w/good show gas after each swab run, Est 150 MCF. Recovered 55 bbl load, total load recovered 270 bbl (31 bbl over). Closed well in. Prep to kill well and pull tubing. | | |

.

Page 22

| NUMBER | FLOWER DRA | W_2_STAT | TE #1 STATE_New Mexico |
|------------------------------------|--------------------------|----------|--|
| FIELD | Wildcat | <u></u> | COUNTY_Eddy |
| ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~ | TD 13450' | PBTD 12 | 284 5' |
| Date | Depth | Days | Remarks |
| 6/24/81 | 13450' TD PB 12845' | 125 | P/Set CIBP, Wolfcamp. After SI 13 hrs TP 2400#. Opened on 32/64" choke to reserve pit, press. bled to 0# in 1/4 hr. RU Roland kill truck and via tubing pumped 55 bbl 10# 2% KCl water. ND Xmas Tree, NU BOP's. Unseated packer and TOH w/2 7/8" tubing and packer. Closed well in, shut down for nite. Prep to |
| 6/25/81 | 13450' TD 11850' PBTD | 126 | set cast iron bridge plug. RU Schlumberger, ran gauge ring and junk basket to 12000'. Set CIBP @ 11885', dumped 35' cement on top. T/Plug at 11850'. RD Schlumberger. RU & Ran Baker Lockset packer & 146 jts 2 7/8" tubing. Closed well in and SD for nite. P/TIH w/tbg. |
| 6/26/81 | 11 | 127 | P/Acidize Wolfcamp. Finished running 2 7/8" tubing (351 joints, 10,937'). RU Dowell and spotted 250 gal. 15% NE Acid from 10937' to 10771'. Pulled 7 joints 2 7/8" tubing. Set Baker Lockset packer at 10721' w/12000# compression. ND BOP's, NU Xmas Tree, tested to 7500# by WKM. Ru Schlumberger w/ 2 1/8" selectfire gun and perf 7" casing as follows: 10892', 10913', 10,915', 10922',10924', 10927' and 10930' (7 shots in 38' interval). RD Schlumberger. Closed well in & shut down for nite. Prep to acidize perforations. |
| 6/27/81 | | 128 | After SI 10 hrs, TP 2800#. RU Dowell and treat w/ 1500 gal 7 1/2% MSR 100 Acid, 15 7/8" ball sealers and 250 gal. previously spotted acid. Formation broke at 5000#. Max. press 7300# w/balls on perfs. Avg. press 6050#, Final press. 4900#. ISIP 4900#, 15" SIP 4600#. Nitrofied all fluid w/1000 SCF/bbl nitrogen. 148 bbl load to recover. RD Dowell. Open to reserve pit w/ TP @ 4600#. Press to 200# in 45 min. First show of gas to burn in 45 min. Flowed 12 hrs on 38/64" choke. TP 200#. Gas Rate 1.25 MMCF w/fine spray of water. All load recovered. Continuing to flow. |
| 6/28/81 | " | 129 | Flowed and tested 7 hrs on 22/64" choke, TP 325#. Gas rate 1.25 MMCF. No water. Closed well in at 2:00 p.m MST for buildup. RD Mack Chase pulling unit. Release |
| 6/29/81 | 11 | 130 | all BOP equipment and tools. Shut in 31 hours for buildup. Broke 3000# gauge in Xmas tree. Will change out gauge today. |
| 6/30/81 | 11 | 131 | Shut in 55 hours, TP 5125#. In last 12 hours TP built 25#. |

.

-

,