| ONTED STATE INTERIOR | NM-22207 |
|---|--|
| DEPARTMET OF THE INTERIOR GEOLOGICAL SURVEX 100 100 100 3821 | 6 IDIAN, ALLOTTEE OR TRIBE NAME |
| GEOLOGICAE SONVER | 7. UNIT AGREEMENT NAME |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different | 8. FARM OR LEASE NAME |
| (Do not use this form for proposals () reservoir, Use Form 9-331-C for such proposals.) | Washington Ranch Storage Project |
| 1. oil gas other Gas Storage Well | 9. WELL NO. |
| 2. NAME OF OPERATOR | 10. FIELD OR WILDCAT NAME |
| El Paso Natural Gas Co. // 3. ADDRESS OF OPERATOR | Washington Ranch Morrow |
| 1000 Using Pldg Midland Texas 79/01 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | _sec, 33, T-25-\$, R-24-E |
| below.) AT SURFACE: 572' FEL & 1707' FNL | 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: | Eddy N. Mexico |
| AT TOTAL DEPTH: | 14. API NO. |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) GR. 3753' |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | division in the second |
| TEST WATER SHUT-OFF | |
| FRACTURE TREAT SHOOT OR ACIDIZE WINDER Report results of multiple completion or zone | |
| REPAIR WELL | (NOTE: Report jesuits of multiple completion or zone) 1 1984 change on Form 9–330.) |
| PULL OR ALTER CASING LIMITIPLE COMPLETE | , T . 2C4 |
| CHANGE ZONES O. | C. D. |
| ABANDON* LJ ARTESI | A, OFFICE |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statingluding estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent.) | nt to this work.)* |
| 1.) Move in and Rig up workover unit, set to | ubing plug. |
| 2.) Remove wellhead and install BOP. | |
| Pull production tubing with snubbing unit | it. |
| 4.) Run permanent packer on wireline and set | t +100' above penfs. |
| | - Committee of the second section of the section of the second section of the section of t |
| 5.) Run production tubing, circulate treated | |
| 6.) Land tubing with latch in sub in packer | |
| 7.) Remove tubing plug, release workover un Subsurface Safety Valve: Manu. and Type | it, return to service. Set @Ft. |
| 18. I hereby certify that the foregoing is true and correct | 15 1004 |
| SIGNED THE Sr. Production | |
| (This space for Federal or State of | fice use) |
| ADDROVED BY 1. Detach to TITLE F. E. | DATE 6/20/84 |

OMITED STATES :