

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED BY  
Form Approved.  
Budget Bureau No. 42-B1424  
AUG 25 1983  
O. C. D.  
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐  
2. NAME OF OPERATOR  
Sundance Oil Company  
3. ADDRESS OF OPERATOR  
1675 Larimer St., Suite 800, Denver, CO 80202  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 2180' FNL, 1780' FEL  
AT TOP PROD. INTERVAL: As above  
AT TOTAL DEPTH: As above  
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  
TEST WATER SHUT-OFF ☐ ☐  
FRACTURE TREAT ☐ ☐  
SHOOT OR ACIDIZE ☐ ☐  
REPAIR WELL ☐ ☐  
PULL OR ALTER CASING ☐ ☐  
MULTIPLE COMPLETE ☐ ☐  
CHANGE ZONES ☐ ☐  
ABANDON\* ☒ ☐  
(other) ☐ ☐

5. LEASE  
NM-14125  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
ARTESIA, OFFICE  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Cottonwood Springs Fed. Comm.  
9. WELL NO.  
1  
10. FIELD OR WILDCAT NAME  
Undesignated Morrow  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Section 18, T.25S., R.26E.  
12. COUNTY OR PARISH  
Eddy  
13. STATE  
New Mexico  
14. API NO.  
30-01S-23841  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3384'. IGR

(NOTE: Report results of multiple completion or zone change on Form 9-331-C)

RECEIVED  
JUN 23 10 16 AM '83  
BUREAU OF LAND MGMT.  
ROSWELL DISTRICT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Attn: Mr. Armando Lopez

1. Set CIBP above Morrow perforations at 11,240'.
2. Spot 200' plug of cement on top of BP.
3. Spot 150' plug of cement from 8700' to 8550'.
4. Spot 100' plug of cement from 5145' to 5045'.
5. Cut off and pull 7-5/8" casing at approximately 3000'.
6. Spot 100' plug of cement across 7-5/8" casing stub, 50' inside and 50' outside of 7-5/8" casing. Verify plug by tagging up.
7. Spot 100' plug of cement from 1740' to 1640'. across 10-3/4" surface pipe.
8. Spot 25 sx cement at surface.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Don Marohcelli TITLE Drilling Manager DATE June 17, 1983

APPROVED PETER W. CLOSTER (This space for Federal or State office use)  
(Orig. Sgd.) PETER W. CLOSTER  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

AUG 23 1983