Faunt 0 221			Length Length Lenn	,	6
Form: 9- -331 (May 1963)	U IED ST		SUBMIT IN TRIP CATE.	Form approve Budget Bures	ed. au No. 42-R1424.
	GEOLOGICAL	THE INTERIOR verse aide)		5. LEASE DESIGNATION AND SUBLIAL NO. NM-13989	
SUNE	ORY NOTICES AND	REPORTS C	IN WELLS	6. IF INDIAN, ALLOTTER	OR TRIBE NAME
(Do not use this f	orm for proposals to drill or to Use "APPLICATION FOR PER	deepen or plug ba MIT—" for such pro	ck to a different reservoir.		
OIL GAS WELL	OTHER			7. UNIT AGREEMENT NA	MU
NAME OF OPERATOR	Tee	• • • • • • • • • • • • • • • • • • •	1997 51	8. FARM OR LEASE NAM	
Wood & Locker	, inc.			Amoco Federa	1
505 N. Big Sp	ring Suite 600, M	idland, TX.	79701	1	
See also space 17 below At surface	port location clearly and in acc	ordance with any S	MAR 21 1987	0. FIELD AND POOL, OF North Hay Ho Springs Pool	110w - Bon
Unit A, 660 F	eet from the North	Line and 99	0 feet from the	1. SEC., T., B., M., OB B. SURVEY OF AREA	
East line			ARTESIA, OFFICE		. • .
. PERMIT NO.	15. ELEVATIONS	(Show whether DF, I		S26,T25S,R2 12. COUNTY OB PARISH	27E
30-015-		(B, 3075'GR		Eddy	IO. BIAIB
	Check Appropriate Box	To Indicate Na	iture of Notice, Report, or O		
				JENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CA	SING	WATER SHUT-OFF	REPAIRING W	
FRACTURE TREAT	MULTIPLE COMPLE	те	FRACTURE TREATMENT	ALTERING CA	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OB ACIDIZING	ABANDONMEN	
REPAIR WELL	CHANGE PLANS		(Other)		
(Other) DESCRIBE PROPOSED OR C	OMPLETED OPERATIONS (Clearly	state all portinent	Completion or Recomple	of multiple completion o tion Report and Log form	n Well n.)
proposed work. If w nent to this work.) *	ell is directionally drilled, give	state all pertinent subsurface locatio	details, and give pertinent dates, i ns and measured and true vertical	including estimated date depths for all markers	of starting any and sones perti-
1. Rig up uni	t and lay down rod	s and null	tubing		
2. Rig up wir	eline truck and se	t C.I.B.P.	@ 5860'. Can with 5	eks of comen	· . •
2. Van In 101	e with tubing and	circulate h	ole with mud. Pull	out of hole with	th tubing.
our a pull	42 Casing from 3	382.			
5. Run in hol Tagged @ 3	e with tubing to 3	430'. Spot	ted 35 sks. of cemen	t. Wait on cen	nent,
6. Pull tubin	g to 2364' and sno	tted 35 eke	. of cement. Wait of		
7. Spotted 35	sks. of cement @	2364'. Wai	t on cement. Could	n cement, Coul	ld not tag.
8. Spotted 12	0 sks. of cement @	2364'. Wa	it on cement. Tagge	d @ 2080'.	1. No. 1.
9. Spotted 35	sks. of cement @	675 '.		•	
 Spotted 15 Clean Cell 	sks. of cement @	70'.			
12. Rig down u	nit and clean loca	ad; install tion.	P & A marker; and c	ut off anchor.	
				P	+ TN-2
				3	+ ID-2 -29-87
.1					PXA
l'a nl			Baber Well Servicing	> Co.	
I hereby certify that the	Dale May foregoing is true and correct		P & A Supervisor		-20-87
1 moll		TITLE		_ DATE	
(This space for Federal	or State office use)				
APPROVED BY		TITLE		32	2087
CONDITIONS OF APPR	OVAL, IF ANY:	**********		DATE	/
	7				
			•		
	* S e	e Instructions of	n Keverse Side		

÷.,

clsf