

Form 3160-5
11 November 1990

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

FORM APPROVEDDesign Review No. 1004-0133
Expires: September 30, 19953. Lease Designation and Serial No.
LG-5340

6. If Indian, Allotment or Tribal Name

7. If Use or Co. Agreement Designation

8. Well Name and No.

OB #5

9. API Well No.

10. Field and Pool, or Exploratory Area
Wsh. Rnch Mor.11. County or Parish, State
Eddy Co., N.M.**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other
Gas Storage Well

2. Name of Operator

El Paso Natural Gas Co.

3. Address and Telephone No.

P.O. Box 1492, El Paso, Texas 79978 (915) 541-2600

4. Location of Well (Range, Sec., T., R., M., or Survey Description)

2310' FNL & 660' FEL**SEC. 32, T-25-S, R-24-E**12. **CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

- ☒ Notice of Intent
- ☐ Subsequent Report
- ☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
- ☐ Recompletion
- ☐ Plugging Back
- ☐ Casing Repair
- ☐ Altering Casing
- ☐ Other

Plug & Abandon

- ☐ Change of Plans
- ☐ New Construction
- ☐ Non-Reserve Fracturing
- ☐ Water Shut-Off
- ☐ Conversion to Injection

(Note: Report results of complete completion on Well Completion or
Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is deliberately closed, give subsurface locations and measures and give vertical depths for all markers and means pertinent to this work.)

Page 1 of 2

- 1) Notify BLM/OCD of intentions to P&A OB #5
- 2) Inspect Location, WH Connection, Deadmen, etc.
- 3) MI & RU PU & Surface Equipment.
- 4) RU Kill Truck & Mud Truck (Premixed) & circ. mud to kill well and load hole w/ minimum 9 #/gal. mud (25 #/bbl. salt gel mixed in 9 #/gal. brine).
- 5) ND WH & NU BOP.
- 6) POOH w/ 2 7/8" Tbg. & Clean/Inspect/Tally for possible salvage.
- 8) RU WL & Run GR to 7150' (top perf. @ 1991').
- 9) RIH w/ 5 1/2" CIBP on WL & set @ 7150'. POOH.
- 10) RIH w/ Cement Bailer on WL & spot 35' Class H cement on top CIBP. POOH.

(Continued on next page)

14. I hereby certify that the foregoing is true and correct

Reservoir Engineer**10/22/92**Signed Dave Brewster

Title

Date

(This space for Signature or Stamp of the well)

Approved by

Title

Date

Continued on next page, if any: