

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a well or reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	<div>RECEIVED BY MAY 27 1985 O.C.D. APPROPRIATE OFFICE</div>
2. NAME OF OPERATOR Quana Petroleum Marline Pet Corp.	
3. ADDRESS OF OPERATOR 4900 Capital Bank Plaza, Houston, Texas 77002 14800 Quorum Drive, Suite 500, Dallas, Texas 75240	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	
14. PERMIT NO. 1980 S line 1980 W line K-9-T-26S R-27E	15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO. NM0557561	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Hay Federal "B" Fed.	
9. WELL NO. 1	
10. FIELD AND POOL, OR WILDCAT Hay Hollow	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
12. COUNTY OR PARISH Eddy	13. STATE N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. - CIBP w/35' cement @ 6600
2. - 100' spud 50 in & out @ 5400 TAG
3. - 100 @ 2460 500
4. - 100 @ 576 to 476 TAG
5. - 50 @ surface

1. Cont. Ret. at 5400' & squeeze 180 SX
W/3 SX on top of Ret.

2. 100' plug at 4800'
3. 100' plug at 2460
4. Cut 5 1/2" csg ~ 1800' 100' stub
5. 100' plug at 520' - Tag
6. 50' surface plug.



18. I hereby certify that the foregoing is true and correct

SIGNED Philip Brooks TITLE Agent

DATE 5-13-85

(This space for Federal or State office use)

APPROVED BY Don Ward TITLE

AREA MANAGER
CARLSBAD REGIONAL OFFICE

DATE 5-21-85

*See Instructions on Reverse Side