

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
DEPARTMENT	☒

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
JUL 11 1984
O. C. D.
ARTESIA, OFFICE

Form O-101
Revised 10-1-79

Sub Indicate Type of Lease
State ☒ Fee ☐
State Oil & Gas Lease
L-6791

SUNDARY NOTICES AND REPORTS ON WELLS

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER _____
2. Name of Operator
Wayne Moore
3. Address of Operator
403 N. Marienfeld, Midland
4. Location of Well
UNIT LETTER H 1980 FEET FROM THE N LINE AND 660 FEET FROM
THE E LINE, SECTION 2 TOWNSHIP 26S RANGE 27E

5. Name of Lease
Aztec State
6. Well No.
#1
11. Field and Pool, or Vicinity
Wildcat - *Permian*

15. Elevation (Show whether DE, KT, GR, etc.)
3124' GL
12. County
Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIATION WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- A. Set cast iron bridge plug at 5700' (top of Bone Springs) and spot cement from 5645' to 5700'. (4-27-83)
- B. Perforate two holes at 4890. (4-27-83)
- C. Pump 1300 sacks class "C" cement, 2% Gel, 5 lbs Salt/sk, .3cfe2, 1 lb cello flake, wt. 13.7 yld = 1.38 (4-28-83)
- D. Ran temperature survey - top of cement 700' from surface.
- E. Perforate 4752 - 4798 with 13 holes. (5-12-83)
- F. Acidize and Frac (5-15-83)
- G. Swab test with oil & gas show (5-17-83)
- H. Put on pump for additional testing (5-25-83)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

7-10-84

Original Signed By
Leslie A. Clements
Supervisor District II

AUG 21 1984