NULLED SIVIES OF THE INTERIOR DEPARTMEN GEOLOGICAL SURVEY

ONITED STATES DEPARTMEN OF THE INTERIOR GEOLOGICAL SURVEY	NM-222U/
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Washington Ranch Storage Project
 oil well other Gas Storage Well NAME OF OPERATOR El Paso Natural Gas Co. ADDRESS OF OPERATOR 1800 Wilco Bldg., Midland, Texas 79701 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1715' FNL & 572' FWL AT TOP PROD. INTERVAL:	9. WELL NO. 16 10. FIELD OR WILDCAT NAME Washington Ranch Morrow 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec., 34, T-25-S., R-24-E 12. COUNTY OR PARISH Eddy 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: HEST WATER SHUT-OFF [] FRACTURE TREAT [] SHOOT OR ACIDIZE [] REPAIR WELL [] MULTIPLE COMPLETE [] CHANGE ZONES [] ABANDON* (other) 17 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statements)	RECEVED BY (NOTE: Report results of multiple completion or zone thange on Form 9-330.) O C D ARTESIA OFFICE ate all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and
necluding estimated and true vertical depths for all markers and zones pertinent to this work.) 1.) Move in and Rig up workover unit, set tubing plug. 2.) Remove wellhead and install BOP. 3.) Pull production tubing with snubbing unit. 4.) Run permanent packer on wireline and set ±100' above perfs. 5.) Run production tubing, circulate treated packer fluid. 6.) Land tubing with latch in sub in packer, remove BOP, install wellhead.	
18. I hereby certify that the foregoing is true and correct SIGNED TITLE ST. Production	n Eng. DATE June 15, 1984