DEPARTMEN OF THE INTERIOR GEOLOGICAL SURVEY	NM-22207 2/ 2/ 7" 6. I. DIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Washington Ranch Storage Project (1)
1. oil gas well other Gas Storage Well	9. WELL NO.
 NAME OF OPERATOR El Paso Natural Gas Co. ADDRESS OF OPERATOR 1800 Wilco Bldg., Midland, Texas 79701 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below) AT SURFACE: 2150' FSL & 2150' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	10. FIELD OR WILDCAT NAME Washington Ranch Morrow 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec., 34, T-25-S., R-24-E 12. COUNTY OR PARISH Eddy 14. API NO.
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING OME OF THE COMPLETE OME OF THE CHANGE ZONES ABANDON* (other)	2 1(NOTE: AReport results of multiple completion or zone change on Form 9-330.) C. D. SIA, OFFICE
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	ent to this work.)*
1.) Move in and Rig up workover unit, set t	uping prug.
 Remove wellhead and install BOP. Pull production tubing with snubbing units. 	it.
3.) Pull production tubing with snubbing un4.) Run permanent packer on wireline and se5.) Pun production tubing, circulate treate	t +100' above perfs. GEW M
5.7 Kull production that 53	
6.) Land tubing with latch in sub in packer	
7.) Remove tubing plug, release workover un Subsurface Safety Valve: Manu. and Type	nit, return to serviceFt.
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Sr. Production	Eng. DATE June 15, 1984
APPROVED BY PLOVAL, IF ANY:	DATE 6/20/84

11 COLON ORDICO CONTRA