

Hay Hollow Federal No. 1 - Sundry Notice To Plug and Abandon

9. Spot 10 sx of cement in top of 8 5/8" casing and errect plug and abandon marker.
10. Prepare to plug and abandon as soon as plan is approved.