

Well: PLU # 52

ID Code:

Posted:

Page: 1 of 1

Depth of Failure (ft.): 00000

Ret. to Prod.? NO

Final? YES

Down (hrs.): Daily 24 Cum:

Job Type: Repair

Service (Workover/Stim/Log/Test/(Re)Complete)

Operations Report: PLU CONTRACT KIL TRUCK. TEST

ANNULUS TO 580 PSI FOR 30 MIN. WELL

BLED TO 540 PSI. OK. TEST WITNESSED

BY CATHY QUEEN BLM CARLSBAD, NM

R.D. KIL TRUCK.

Repair Section			Service Section	Cost Section (Estimates)
Failure 00	Cause 21	Contractor	Service 70	Pulling Unit
00 None	21 Not Applicable	Operator	70 None	Rods / Tubing
01 Pin Break	22 Corrosion		71 Workover	Pump Truck 350
02 Box Break	23 Corr.-Polymer		72 Log-Test	Co. Supervision 100
03 S.H. Box Break	24 Handling Damage	40 Brunson	73 T.A.	Rentals
04 Cplg. Unscrewed	25 Under Torque	41 Busters	74 Plug	
05 Wrench Flat Break	26 Over Torque	42 Cobra	75 Press. Survey	
06 F.G. End Connector	27 Rod Wear	44 DA & S	76 Change Lift	
07 Steel Rod Body	28 F.G. Fatigue	45 Dan Mar	77 (Re) Complete	
08 F.G. Rod Body	29 H ₂ S Embrittlement	46 Hercules	78 Swab	
09 Rod Pump	30 Gyp. Build-Up	47 Jackson	79 Other (Explain)	
10 Hydr. Pump (Pistol)	31 Overstressed	48 Longhorn		
11 Hydr. Pump (Jet)	32 Other (Explain)	49 M & W		
12 Elec. Sub. Pump		52 Pool		
13 Tubing Leak		53 Pride		
14 Casing Leak		54 R & H		
15 Pump Jack		55 Ram		
16 Tubing Stuck		56 Standard		
17 Other (Explain)		57 SWC		
20 (Reserved)		58 Wellco		
		59 WellTech		
		60 White		
		61 Other		
	Size 80	District & Production Foreman Monahans		Services:
	80 Not Applicable	91 W.C. Collins		
	81 1/8"	92 C.K. Jenkins		
	82 1/4"	99 M.G. Waygood		
	83 3/8"	Kermil		
	84 1.0"	94 J.D. Robinson		
	85 1.2"	95 L.D. Antley		
	86 1.25"	96 R. Robertson		
	87 K-Bar	Sundown		
	88 2 1/4"	97 J.R. Field		
	89 2 1/2"	98 R.T. Srader		
	90 Other (Explain)	101 G.D. Davis		
		100 Other		
Work Summary and Other Remarks (for Permanent Record):				

Pump Out # Make Pump In # Make LRP

Size Type Size Type LPC

Condition Remarks

