

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

MAR 22 '90

WELL API NO.	3001524152
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG 349

SUNDRY NOTICES AND REPORTS ON WELLS (ARTESIA, OFFICE)  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Delaware River
2. Name of Operator Wayne Moore	8. Well No. 1
3. Address of Operator 403 N. Marienfeld, Midland, Texas 79701	9. Pool name or Wildcat Red Bluff Delaware Gas
4. Well Location Unit Letter G : 1980 Feet From The N Line and 1980 Feet From The E Line Section 10 Township 26 Range 28 NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2997.8' FL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 3000'
  2. Spot 35 sx cement on top of CIBP
  - \* 3. Cut and pull 1600'+- 9-5/8" pipe
  4. 45 sx (100') plug 1650' - 1550'
  5. 100' plug 450' - 350'
  6. Surface plug and marker
- Mud in hole and required plugs will be tagged. To be plugged in April 1990.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom E. Moore TITLE Operations Manager DATE 3-20-90  
TYPE OR PRINT NAME Tom E. Moore TELEPHONE NO 915-682-869

(This space for State Use)

APPROVED BY Daniel Moore TITLE \_\_\_\_\_ DATE 4/3/90  
CONDITIONS OF APPROVAL, IF ANY: \*