For <b>m 3160–5</b> (July 1989) (Formerly 9–331)		N D STATES NT OF THE IN LAND MANAGEM		CONTACT RECEIVI≻ OFFICE FOR NUMBE OF COPIES REQUIRL (Other instructions on re side)	verse	BLM Roswell Dist Modified Form No NM060-3160-4 5. LEASE DESIGNATION / NM-13997	•	
	form for proposals to	o drill or to deepen or OR PERMIT-" for such	plug back to		IVED	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
1. OIL CAS WELL WELL	OTHER			OEC 1	0 '90	7. UNIT AGREEMENT NA	ME	
2. NAME OF OPERATOR Meridian Oil Inc.				O. C		8. FARM OR LEASE NAM Brushy Federal	E	
3. ADDRESS OF OPERATOR 21 Desta Dr.,		9705		3a. AREA CODE & PROVE NO. 915-686-5600		9. WELL NO.		
<ul> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface</li> <li>330' FNL &amp; 1700' FWL</li> </ul>					10. FIELD AND POOL, OR WILDCAT Brushy Draw (Delaware) 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
14. PERMIT NO.		15. ELEVATIONS (Show	whether DF.			Sec. 35, T26S, 12. COUNTY OR PARISH	R29E	
14. PERMIT NO.		2862' GR.				Eddy	NM	
16.	Check App	ropriate Box To	Indicate	Nature of Notice, F	Report	, or Other Data		
,	NOTICE OF INTENTION	<b>'O</b> :		s	UBSEQUEN	T REPORT OF:		
TEST WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) Add Mor	e Delaware Pa		x	Completion or	Recomple	REPAIRING W ALTERING CA ABANDONMEI multiple completion on tion Report and Log for	SING	
17. DESCRIBE PROPOSED ( posed work. If we work.)*	OR COMPLETED OPER ell is directionally d	ATIONS (Clearly state al rilled, give subsurface	l pertinent det locations and	ails, and give pertinent date measured and true vertical	es, incluc depths f	ling estimated date of s or all markers and zone	starting any pro- as pertinent to this	

Recomplete to add more Delaware pay (procedure and well bore diagrams attached).

18. I hereby certify that the foregoing is true and correct SIGNED Trabal L. Brank haut	TITLE	Sr. Staff Env./Reg. Spec.	DATE	05 December 1990
(This space for Federal or State office use)				
APPROVED BY	TITE		DATE	

## \*See Instructions on Reverse Side

## Brushy Federal No. 1 Brushy Draw Field Eddy County, New Mexico

Project Engineer:	K. L. Midkiff	Office:	(915) 686–5714
		Residence:	(915) 686-8650

- 1. MIRU PU, ND WH, NU BOP. POOH with rods, pump and tubing. LD rods.
- 2. RIH with casing scraper to PBTD. POOH. RIH with treating packer to 4800', set packer. Mix 10 gallons of Unichem Techni-Clean 420 in 10 barrels of 2% KCl water and pump down tubing at 1 BPM. Mix 2 drums of Unichem XFE converter in 8 barrels of 2% KCl and pump down tubing at 1 BPM. Flush to bottom perf with 2% KCl water. Release packer and pull up to 3500'. Load hole with treated 2% KCl water (same as breakdown fluid) and POOH.
- 3. Set CIBP at 3400'. Test casing and plug to 3500 psi.
- 4. RIH with 2 1/2" casing gun and perforate 2 SPF at 2956'-2978' (44 shots), 2982'-2990' (16 shots), and 2993'-3012' (38 shots). POOH with wireline.
- 5. MIRU stimulation company. NU surface lines and test to 3000 psi. Breakdown Bell Canyon with 3000 gallons of treated 2% KCl water and 147 7/8" RCNBS (Sp. Gr. = 1.3). Pump down casing. Run gauge ring and junk basket to knock balls off.

Treating Rate =	8 BPM
Anticipated Pressure =	1400 p <b>si</b>
Maximum Pressure =	2800 psi

6. Fracture stimulate Bell Canyon down casing with 20000 gallons of 65-Quality  $N_2$  foam and 64100 lbs of 12/20 mesh Ottawa Sand. Pump at 20 BPM.

Treating Rate =	20 BPM
Anticipated Pressure =	1500 psi
Maximum Pressure =	2800 psi

748:4

Brushy Fed. No. Procedure Page Two

Stage	Fluid	ppg	<u>Volume (gal)</u>
Pad	65-Q Foam	0	7000
1	65-Q Foam	1-3 (Ramp)	3000
2	65-Q Foam	3-8 (Ramp)	8000
3	65-Q Foam	8	2000
Flush	65-Q Foam	0	1750

Shut well in for 90 minutes, then start to flow well back.

7. RIH with bit and knock out CIBP. Clean out ot PBTD. RIH with MA, PN, SN and tubing to 2900'. Run pump, 2075' of 7/8" steel rods and 825' of 1" fiberglass rods (both from Pecos Fed. #1-Y) ND BOP, NU WH. Space out and put on pump. Production personel will lower tubing in 10 days. Report rates to Midland office. Also run Stanly Filter with pump (contact Jerry Sparks for filter).

Approved:\_\_\_\_

Date:\_\_

T J. Harrington







Eddy County, New Mexi	Brushy Draw Field	Brushy Federal No. 1
tico	<u>a</u> .	-

## MRCHANICAL DATA

Tubing		Casing	Production	Casing	Intermediate	Surface Casing	Type Tubular:
2 3/8		4 1/2	4 1/2		9 5/8	13 3/8 12.715	0D (in)
1.995 4.7	DV To	4.090	4.052		9 5/8 8.921	12.715	ID (in)
4.7	DV Tool at 4291'-4294'	9.5	10.5		36	48	Weight (#/ft)
N-80	1'-4294'	<b>K-</b> 55	K-55		K-55	H-40	Grade
8rd EUE			ł				Conn.
4900		4673-5991	0-4673		2914	320	Depth (ft)
11780		3310	4010		2020	770	Collapse (psi)
11200		4380	4790		3520	1730	Burst (psi)
0.00387		0.0162	0.0159		0.0773	0.1570	Capacity (BPF)
	(081)	3000			Surf	Surf	TOC (ft)