

c151

N.M. Oil Cons. Division
211 S. 1st Street
Albuquerque, NM 88210-2834

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
J.C. Williamson

3. Address and Telephone No.
P.O. Box 16, Midland, TX 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
2310' FEL & 230' FSL
Sec. 28, T-26-S, R-30-E

5. Lease Designation and Serial No.
NM-17225-B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Abby Federal #3

9. API Well No.
30-015-24763

10. Field and Pool, or Exploratory Area
Ross Draw Delaware

11. County or Parish, State
Eddy County, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose: Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Set 4-1/2" CIBP @ 3327', cap w/ 35' of cmt.
2. Circulate the hole w/ mud laden fluid.
3. Cut & pull 2960' of 4-1/2" csg.
4. Spot 35 sx 50' inside & 50' outside 4-1/2" csg. Stub. Tag.
5. Cut & pull 1000'+ of 8-5/8" csg.
6. Spot 65 sx 50' inside & 50' outside of 8-5/8" csg. Stub. Tag.
7. Spot 65 sx 410'-310'. Tag.
8. Spot 20 sx 50' - 0'.
9. Install dry hole marker. Clean location.

RECEIVED
APR 15 2001

14. I hereby certify that the foregoing is true and correct

Signed David R. Glass Title Agent Date 2-12-01

(This space for Federal or State official use)

Approved by (ORIG. SGD.) DAVID R. GLASS Title PETROLEUM ENGINEER Date FEB 15 2001

Conditions of approval, if any:

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

Title 18 U.S.C. § 1001 makes it a crime for any person to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED

FEB 13 2001

BLM

ROSWELL, NM