

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-24836
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-1171
7. Lease Name or Unit Agreement Name	Flower AGA State
8. Well No.	1
9. Pool name or Wildcat	Red Bluff Brushy Canyon

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>3</u> Township <u>26S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>2937' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-30-95 - Notified Mike Stubblefield w/OCD-Artesia of commencing plugging operations. Moved in and rigged up pulling unit. Nipple down pumping unit. POOH with rods and pump. Nipple up BOP. Released tubing anchor. POOH with tubing, seating nipple, perforated sub, tubing anchor and 2 joints of tubing. Rigged up wireline. TIH w/4-1/2" CIBP and set at 5989'. Rigged down wireline. TIH with tubing and tag CIBP. Spot 63 bbls plug mud from 5989-2000'. Mixed and pumped 15 sacks Class C cement from 5989-5769' (in 4-1/2" casing). POOH with tubing to 4680'. Mixed and pumped 25 sacks Class C cement from 4680-4316' (in 4-1/2" casing). POOH with tubing to 3460'. Mixed and pumped 25 sacks Class C cement from 3460-3096' (in 4-1/2" casing). POOH with tubing to 2850'. Mixed and pumped 35 sacks Class C cement from 2850-2335' (in 4-1/2" casing). POOH with tubing to 2330'. Reverse circulate clean. POOH with tubing. Shut down for night.

7-1-5-95 - Notified Ken Livingston w/OCD-Artesia on cement plugs. TIH with tubing and tag top of cement at 2305'. POOH with tubing. Nippled down BOP and wellhead. Rigged up welder and welded on 4-1/2" pull nipple. Rigged up casing jacks. Pulled casing slips.

CONTINUED ON NEXT PAGE:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE July 12, 1995
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Mike Stubblefield TITLE Field Rep. I DATE 8-18-95
CONDITIONS OF APPROVAL, IF ANY: