Form 3160	)-5
(November	r 1983)
(Formerly	9-331)

## UNIT STATES SUBMIT IN TRIPLI 50 DEPARTMENT OF THE INTERIOR verse side) 5.1

Form approved.	
Budget Bureau No. 10	004-0135
Expires August 31, 1	985 <i>(</i>

ა.	LEASE	DESIGNATION	AND	SERIAL	NC
NM-2/177					

-			!
L	AND MANAGEMENTOLS,	RECEIVED	NM-24777

BUREAU OF LAND MANAGEMENTELE, FRECEIVED					1	NM-24777		
	SUNDRY NOT	ICES AND R	EPORTS	ON WELL	S	6. 1	F INDIAN, ALLOTTE	E OR TRIBE NAME
(Do not	use this form for proportion Use "APPLICA"	ania to drill or to d ATION FOR PERMI	leepen or plug T" for such	back to a different propos <b>i</b> ls.) 17	nt reservoir.			
<u>i</u> .				—— JAN 17—	<del>-11-58 (d) '</del>	<del>89</del> 7. 1	NIT AGREEMENT N.	AME
WELL X	GAS OTHER			e · ÷				
2. NAME OF OPE	· · · · · · · · · · · · · · · · · · ·			7.1.1.	<del></del>	8. #	ARM OR LEASE NA	M.E.
	J.C. Will	iamson				-	Ingram-Groo	ms Federal
3. ADDRESS OF	OFERATOR					9. 7	TBLL NO.	
	P.O. Box		idland, T	ş,	ECEIVED		1	
1. LOCATION OF See also spuc	WELL (Report location c	learly and in accor	dance with an	y State requireme	nts.•	10.	FIELD AND POOL, C	R WILDCAT
At surface							East Brushy	<del></del>
	/10' FSL	& 660' FWL		f	EB 1'89	11.	SEC., T., R., M., OR SURVEY OR AREA	BLK. AND
							0 7 0 6	a n 20 n
14 penting No.		15. ELEVATIONS (	Show whather r	P PT CP etc.)	O. C. D.		Sec. 9 T-26	
14. PERMIT NO.	4070	İ			RTESIA, OFFICE			New Mexic
30-015-24	49/8	3076' G	K			<u> </u>	Eddy	New Mexic
16.	Check Ai	opropriate Box 1	o Indicate	Nature of Not	ice, Report,	or Other	Data	
	NOTICE OF INTEN	TION TO:		l	<b>B</b> UI	BSEQUENT I	REPORT OF:	
TEST WATER	SHUT-OFF	PCLL OR ALTER CAS	ING	WATER	SHUT-OFF		REPAIRING	WELL
FRACTURE T	()	MULTIPLE COMPLET			E TREATMENT		ALTERING C	
BHOOT OR A	<del></del>	ABANDON*		SHOOTII	G OR ACIDIZING		ABANDONME	NT* X
REPAIR WEL	.L	CHANGE PLANS		(Other)				
(Other)							ultiple completion Report and Log fo	
17. DESCRIBE PRO	DPOSED OR COMPLETED OFF work. If well is direction	CRATIONS (Clearly 8	tate all pertine	ent details, and	ive pertinent d	lates, inclu	ding estimated da	te of starting any
nent to thi		onany drines, give	adaban tacc .co					- mmc 40=05 <b>,</b>
10 00 00	n: 1 n 1	11	Ch.		hala 11/+1	. ~		
12-08-88	Rigged up Bab						1 1	
12-12-88	COOH w/tbg, s				of cement	on plu	g, circ hol	.e
	w/150 bbls 9.							
12-13-88	Set 5-1/2" cs							
12-14-88	Spotted 100' tagged plug (	4185', hel	rom 4292 d OK, CO	-4192', COI H to 3360'	d w/10 sta , set 100'	ands tb cmt p	g, WOC 4hrs lug from 33	3., 360-3260'.
	COH w/tbg. SI						CC . 11 h	
12-15-88	GIH w/tbg, ta 8-5/8" csg @	2540', woul	d not cor	me free. Si	DFN			
12-16-88	0.0001 77 /0.0							
12-19-88	Tagged plug (plug @ 840',	d 1939', hel held OK, se	t 50' su	rface plug	cmt plug , installe	ed dry	hole marker	S, Lagged
12-20-88	Job completed	d, rigged do	wn plugg	ing unit.				
	·						$\rho_{a}$	t0-2
		•					1000	ID-2 24-89
							, , , , , , , , , , , , , , , , , , ,	Y A
							Г	<del>4</del> .14
		<u> </u>						
18. I hereby cer	tify that the foregoing	is true and correct		D 1 !			01-	13-89
SIGNED	(61)	7.769	TITLE	Producti	on		DATE	
(This space	for Federal or State off	lce use)						
	<i>t</i>		mimire				DATE /	31-89
APPROVED	S OF APPROVAL, IF	ANY:	TITLE				~	<del></del>
_	to ad an !	, ,						
	Autological Control	2 1 1 1 1 2 d						
s	61,465 ∤65.5,5.54 15 05	omedine "•\$	ee Instructio	ns on Reverse	Side			
		ŭ						