

U. S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDY NOTICES AND REPORTS ON WELLS

EX-101 CONS. COMMISSION
SUBMIT IN TR CATE*
(Other, Instructively)
88210

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED BY BUREAU OF LAND MANAGEMENT

SUNDY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☒ OTHER ☐
2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

P.O. Box 16 Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FEL 1980' FSL
1960

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2899.5 GR

5. LEASE DESIGNATION AND SERIAL NO.

NM 13997

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

EP-USA

9. WELL NO.

7 - Y

10. FIELD AND POOL, OR WILDCAT

Brushy Draw Delaware

11. SEC., T., R., M., OR BLK. AND

Sec. 26

T-26-S, R-29-E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pursuant to BLM instructions obtained January 6, 1985, the J.C. Williamson EP-USA #7 was plugged and abandoned on January 7, 1985, and witnessed by a BLM representative.

Well was drilled to 472'. On 1-4-85 tried to run 13 3/8" surface casing, but wouldn't go. Went in hole to clean and ream. Bit stuck at 146'. Recovered all but one 30' x 6 1/8" drill collar and 17 1/2" bit. Top of fish at 112'. No casing in hole. Fill found at 70'. Set plug w/100sx Haliburton thickset. Set plug w/35 sx Class "C", 4% CaCl₂, got 1' fill. Set 3rd plug w/50 sx same, got 1' fill; used 6 yards pea gravel, got 1' fill; 35 sx plug, got 8' fill. Filled hole w/12 yards pea gravel, got 1' fill, top of fill at 54'; hole now dry. Filled hole w/10 1/2 yards, 5 sx/yard ready mix concrete; filled hole to top of celler. Placed metal plate in wet cement. Will install dry hole marker as soon as available, and when dry hole marker will not interfere w/future drilling operations.

Rig will be skid 20' to the south of the EP-USA #7. New well will be J.C. Williamson EP-USA #7-Y.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side