

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other Instructions on reverse side)

Budget Bureau No. 1004-0115
Expires August 31, 1988

5. LEASE DESIGNATION AND SERIAL NO. **21SF**
NM-27647

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Exxon Federal

9. WELL NO.

10. FIELD AND SURFACE WELLS
1
J. CORRA X CANYON
Wildest-BoneSpring

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 31, T25S, R30E

12. COUNTY OR PARISH 13. STATE

Eddy New Mexico

SUNDRY NOTICES AND REPORTS ON RECEIVED
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

DEC 07 '88

2. NAME OF OPERATOR

O. C. D.

ADDRESS, OFFICE

3. ADDRESS OF OPERATOR

P. O. Box 1591 Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

760' FSL and 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GK, etc.)

3082.7 GR

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X
X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Fully state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Move in And Rig up. Pull Rods and Lay Down
2. Load Hole w/ 10# mud
3. Set Plugs AS FOLLOWS - #1 7477' to 6920' w/ 35 SKS. AND TAQ
- #2 4100' TO 4000' 15 SKS.
- #3 3381' TO 3280' 15 SKS. AND TAQ PLUG
- #4 400' TO 300' w/ 15 SKS.
- #5 SPOTTED 15 SKS. TOP HOLE AND SET PSA MARKER

Part ID-2
12-23-88
P+R

18. I hereby certify that the foregoing is true and correct

SIGNED **S.S. Siverak**

TITLE **operations Manager**

DATE **10/14/86**

(This space for Federal or State office use)

ORIG. SGD. PA/GRI

APPROVED BY **CHIEF MINERAL RESOURCES**

TITLE

DATE

12-6-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side