

DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for permits to drill or to complete a well back to a ditch or reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☒ GAS ☐ OTHER ☐

2. NAME OF OPERATOR

MAX WILSON, INC. ✓

3. ADDRESS OF OPERATOR

P. O. Drawer 1978 - Roswell, NM 88260

4. LOCATION OF WELL (Report location clearly and in accordance with any State law.  
See also space 17 below.)  
At surface

1,980' FSL and 1,980' FWL

14. PERMIT NO.

3001525274

15. SITUATIONS AND WEATHER (If applicable)

3,269' KB (GL-5')

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

TEST WATER SAMPLES

FRACURE LOGS

REPAIR OR ABANDON

REPAIR WELL

(Other)

FIELD OR ALTERNATE

REPAIR OR ABANDON

ABANDON\*

CHANGE PLANT

SUBSEQUENT REPORT OF:

REPAIR OR ABANDON

REPAIR OR ABANDON

REPAIR OR ABANDON

OTHER

REPAIRING WELL

ALTERING Casing

ABANDONMENT\*

X

17. DESCRIBE IN DETAIL the proposed operation or other activity and provide a detailed description of the well, including pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface location and name of well and true vertical depths for all markers and zones pertinent to this work.

Covered pit, ripped and seeded, put up road barrier.  
Proper dry hole marker is in place.

18. I hereby certify that the foregoing is true and correct.

SIGNED MAX WILSON

President

DATE 2/27/86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

\*See Instructions on Reverse Side