REDEIVED

NM OIL CONS COMMISSION

Drawer DD

Form 3160-5 (June 1990)

Artesia, NM 88210 9 11 DEPARTMENT OF THE INTERIOR

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

NM 27459

6. If Indian, Allor

	İ
SUBMIT IN TRIPLICATE WOOR 10/4	7. If Unit or CA, Agreement Designation
ON Well Gas DRY HOLE	NA 8. Well Name and No.
2. Name of Operator  General Atlantic Resources, Inc.  ARTESIA, OFFICE	Monsanto Fed #1
3. Address and Telephone No. 410 17th Street, Suite 1400, Denver, CO 80202 (303) 573-5100	30-015-25276  10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Unnamed
660' FSL & 1980' FWL, SESW Section 22, T25S-R26E.	11. County or Parish, State
	Eddy NM

2.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
	TYPE OF SUBMISSION	TYPE OF A	ACTION
	Notice of Intent	Abandonment	Change of Plans
	Subsequent Report	Recompletion Plagging Back	New Construction Non-Routine Procturing
	Final Abandonment Notice	Cuing Repair Altering Cuing Cit Other PLUG WELL	Water Shair-Off Conversion to Injection
		•	(Note: Report results of multiple completies on Well Completion or Recompleties Report and Log form.)

- 1) Place Bridge Plug at 2020', cap with 35 sx class "C" neat cement.
- 2)Place CIBP at 1835', cap with 35 sx class "C" neat cement.
- 3)Cut 4-1/2" casing at 1190', place 100' plug Class "C" neat, 50' inside stub and 50' outside, top cement at 1140', bottom at 1240'. (tag plug)
- 4)Place 100' plug from 920' to 1020' class "C" neat.
- 5)Place 100' plug at 150' to 250' class "C" neat, base of 8-5/8" casing.
- 6)Place 10' plug at surface class "C" neat.
- 7)Cut off well head and weld on flat marker, clean up site.

14. I hereby certify that the foregoing is true and correct Signed	Scott M. Webb  THE Regulatory Coordinator Dec 10/26/94	
(This space for Federal or State office use)  Approved by (ORIG. SGD.) JOS G. LARA	PETROLEUM ENGINEER	
Conditions of approval, Il any: Sec attached.	PETROLEUM ENGINEER  1. 14/94  1. 14/50 tag plug across 4/2 " csg stub	

## BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Permanent Abandonment of Wells on Federal Lands

## Conditions of Approval

- 1. <u>Approval:</u> Plugging operations shall commence within 90 days from the approval date of plugging procedure.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (505)887-6544; for wells in Lea County call (505) 393-3612.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" , for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H" , for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

- 6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show <u>date</u> well was plugged.

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.