

RECEIVED

Form 3160-5
(June 1990)

UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 15302

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Gulf "5" Federal # 1

9. API Well No.

#30-015-25312

10. Field and Pool, or Exploratory Area

Rustler Bluff Atoka

11. County or Parish, State

Eddy

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Bettis Brothers Inc.

3. Address and Telephone No.

500 West Texas, Suite 820, Midland, TX 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310 FNL & 660 FEL of Sec. 5, TWD 25 S, Rg 29 E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set a 4-1/2" CIRP on W.L. at 12,300 .
2. Cap with 35' cement.
3. Set a 200' cement plug 10-100'-10,300'.
4. Circulate hole with 9.5# gal Brine mud.
5. Set a 100' cement plug 9750'-9860'.
6. Cut 7-5/8" casing at 8000' and pull.
7. Set a 200' stub plug 7900'-8100'. (Tag plug)-100' inside and 100' outside 7 7/8" casing
8. Set a 100' plug 6600'-6700'. (Tag plug)
9. Set a 200' plug 2600'-2800'. (Tag plug)
10. Set a 100' plug 550'-650'.
11. Set a 50' plug from Surface to 50'.
12. Weld a cap and dry hole marker on stub (minimum 5' below ground level)
13. Clean-up location and rip caliche on location and roads per BLM requirements..

14. I hereby certify that the foregoing is true and correct

Signed *[Signature]*

Title Agent for Operator

Date January 5, 1993

(This space for Federal or State office use)

Approved by *[Signature]*

Title

Date 1-14-93

Conditions of approval, if any: