

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to different reservoirs. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. CIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NM-20966
2. NAME OF OPERATOR J.C. Williamson	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 16 Midland, Texas 79702	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1880' FNL & 660' FEL	8. FARM OR LEASE NAME New Era Federal
14. PERMIT NO. 30-015-25326	9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3056.8' GR	10. FIELD AND POOL, OR WILDCAT Undesignated Delaware
	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA Sec. 19, T26S, R30E
	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 05-11-87 Set CIBP @ 5425', put 35' of cement on top of plug. Set 100' plug from 3300-3200'.
- 05-12-87 Shot 5-1/2" casing @ 2525', COH and laid down 63 joints 5-1/2", shot 8-5/8" @ 2368', casing loose, SD/day.
- 05-13-87 COH w/8-5/8" and laid down 61 jts. 8-5/8" casing. Unable to stab into 5-1/2" stub @ 2525'. Set 100' plug from 2368-2268' w/tubing. (BLM notified and approved setting this plug in this manner) WOC 8 hrs. tagged plug, held OK, COH w/tubing set 100' from 1600-1500', did not tag as per BLM instructions, set 100' plug from 725-625', SD/day.
- 05-14-87 Tagged plug @ 625', held OK, COH w/tubing, set surface plug @ 50'- surface. Rigged down unit. Installed dryhole marker.

ACCEPTED FOR RECORD

SJS

JUN 5 1987

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Jan Pfister TITLE Production DATE 05-29-87

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Approved as to _____ well bore.
Liability under bond is not void until
surface reclamation is completed.

*See Instructions on Reverse Side

Post ID-2
6-19-87
P&A