

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other Instructions on Reverse Side)  
COMMISSION

Form approved.  
Budget Bureau No. 1004-0135 **CKF**  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO LC-068282-B
2. NAME OF OPERATOR Hanson Operating Company, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
3. ADDRESS OF OPERATOR P. O. Box #1515, Roswell, New Mexico 88202-1515		7. UNIT AGREEMENT NAME N/A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  2310' FSL & 950' FWL, Unit L, NW $\frac{1}{4}$ SW $\frac{1}{4}$		8. FARM OR LEASE NAME HANSON FEDERAL
14. PERMIT NO.		9. WELL NO. 17
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3119' GR		10. FIELD AND POOL, OR WILDCAT North Mason (Delaware)
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T. 26S, R. 31E
		12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING **XX**

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Following the perfs @ 6290 - 6297', and the acidizing of same, swbd 1 run, fl 3500' f/surf (SW w $\frac{1}{2}$  gal free oil). Trip Haliburton cmnt rtmr @ 6288'. Sqz perfs @ 6290 - 6297'. Mix 175 sx Type "H" cmnt. Pmp into perfs in stages. Sqz to 2000#. Rev out 2 BBLS cmnt.

Perf f/6206' - 6270' (1 JSPF - 15 shots).

Acidized with 1500 gals NE acid.

Swb 78 BF, total 108 BF. Swb to SN, 7 runs off seat. Total 11BF. Swbg FW.

Swb off SN. Made a run every hour f/11:00 a.m. - 3:00 p.m. - 1 BF per hr.

ACCEPTED FOR RECORD

JAN 8 1986

CARISPAE ALA 11700

18. I hereby certify that the foregoing is true and correct

SIGNED Brenda R. Godfrey

TITLE Production Analyst

DATE 01/02/86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side