

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-068282-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

Hanson Federal Batt. #2

9. WELL NO.

#17

10. FIELD AND POOL, OR WILDCAT

North Mason (Delaware)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 25, T. 26S, R. 31E

12. COUNTY OR PARISH

13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Hanson Operating Company, Inc.

3. ADDRESS OF OPERATOR

P. O. Box 1515, Roswell, New Mexico 88202-1515

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface

Sec. 25, T. 26S, R. 31E, Unit L, 2310' FSL & 950' FWL, NW $\frac{1}{4}$ SW $\frac{1}{4}$

14. PERMIT NO.

30-015-25444

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3119' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANT ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \* The well was plugged & abandoned in the following manner on 02-22-92 thru

02-26-92:

- 1). Tag cem on top fo CIBP @5609'.
- 2). Set a CIBP @4050' & capped w/5"sx (35!) Class C cem. to isolate perf @ 4136-4163'.
- 3). Cut off 5 $\frac{1}{2}$ "csg @2830' & pulled 70 jts 2830' of 5 $\frac{1}{2}$ "csg.
- 4). RIH w/tbg to 2880', circ hole w/90 bbls of 9# gelled fluid.
- 5). Pmp 30 sx Class C cem w/2% CaCl @2880'. 50' in & 50' out of 5 $\frac{1}{2}$ " csg.
- 6). Tagged plug @2738'.
- 7). Perf 8 $\frac{5}{8}$ "csg @1020'.
- 8). Pmp 67 sx Class C cem w/2% CaCl 150' outside 8 $\frac{5}{8}$ " & 13 $\frac{3}{8}$ "csg annulus & 50' inside 8 $\frac{5}{8}$ " csg. Tagged plug @965'.
- 9). Pmp 10 sx Class C cem w/2% CaCl from 50' to surface.

Install dry hole marker, cut off anchors & clean location,

Jim Amos w/BLM gave verbal to proceed w/plugging on 02-24-92.

Post ID-2  
3-20-92  
P4A

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Analyst

DATE 03-05-92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side