

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

AMENDED

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

APR 21 '88

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		ARTESIA, OFFICE	7. Unit Agreement Name
2. Name of Operator Inco Investments Corporation			8. Farm or Lease Name Inco-State
3. Address of Operator 16610 N. Dallas Pkwy. Suite 1200, Dallas, Texas 75284			9. Well No. 1
4. Location of Well UNIT LETTER P, 990 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 26S RANGE 28E NMPM.			10. Field and Pool, or Wildcat Wildcat (Delaware)
15. Elevation (Show whether DF, RT, GR, etc.) 2994' Ground		12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to Plug and Abandon well in the following manner:

Plug #1 - Cast Iron Bridge at 2600'. Dump bailer to drop 5 sx cement on top of bridge plug.

Plug #2 - *Lead hole w/mud* 35 sx across stub of 5 1/2" casing. 2000' ± TAG.

Plug #3 - 30 sx 750-850'

Plug #4 - 35 sx @ 425-325. (Across 8 5/8" shoe)

Plug #5 - 10 sx at surface. Install Tombstone and level location and clean.

Plugging

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John M. C. Rutledge TITLE Agent DATE 4/20/88

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE APR 29 1988

CONDITIONS OF APPROVAL, IF ANY: