

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26105
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1085
7. Lease Name or Unit Agreement Name East Apple State Unit
8. Well No. 1
9. Pool name or Wildcat Undesignated Canyon
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3026' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER RECOMPLETION <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 5 Township 26S Range 28E NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforate & Treat Canyon ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-15-91. RU. Pull rods, pump, tubing. Set RBP @ 6000', packer above, and tested. POOH w/packer. Perforated 5115-5145' w/19 .40" holes as follows: 5115-17, 5121-24, 5127-29, 5132, 34, 5138-40, 5143-45. WIH w/packer and set @ 5000'. Acidized perfs 5115-5145' w/2000 gals 7½% NEFE HCL acid. Swabbed dry. Frac'd perfs 5115-45' w/5000 gals 40# Purgel w/900# 20/40 sand. Flowed back and swabbed well. Swabbing from seating nipple, 2-3% oil cut on last 3 runs. Set pump and pump tested.
3-6-91. RU. Pull rods and pump. RIH w/RBP with ball catcher and packer. Set RBP @ 5050' and tested to 2000#. POH. Perforated 4765-4991' w/31 .40" holes as follows: 4765-72' (8 holes), 4857, 59, 70, 71, 79, 82, 84, 88, 90, 92, 94 and 4896' (12 holes), 4981-91' (11 holes)
3-8-91. Acidized perfs 4981-4991' w/1000 gals 7½% NEFE acid. Acidized perfs 4857-4896' w/1500 gals 7½% NEFE acid. Acidized perfs 4765-4772' w/1000 gals 7½% NEFE acid.
3-15 - 16-91. Swabbing well and recovering load.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-18-91
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE MAR 21 1991

CONDITIONS OF APPROVAL, IF ANY: