

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-30886-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yeso Hills Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat Bone Spring

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 18: T26S, R25E

12. COUNTY OR PARISH

13. STATE

Eddy

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Strata Production Company

3. ADDRESS OF OPERATOR

648 Petroleum Building, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below)

At surface

460' FSL & 1780' FEL

14. PERMIT NO.

API-30-015-26278

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3839'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

The Yeso Hills Federal was plugged and abandoned in the following manner:

- 5 1/2" CIBP w/ 4050' as per telecon. w/ Frank S. Morgan 10/31/92 D.H.E.
6/3/91: 1) Circ hole w/ gelled fluid
2) Set 1st 50' plug @ 4050' to 4000' w/ 5 sx CL "C" Neat
3) Set 2nd 200' plug @ 1265' to 1065' w/ 20 sx CL "C" Neat
4) Set 50' surface plug w/ CL "C" Neat
5) All equipment removed

7/25/91: Have H & H make final cle
and anchors, rip location
Finalized.

1 pits, cut off wellhead
1. Set Dry Hole marker.

on the way

18. I hereby certify that the foregoing is true and correct

SIGNED

Régina Finley

TITLE

Production Analyst

DATE 11/21/91

(This space for Federal or State office use)

APPROVED BY

David H. Glass

TITLE

DATE

3 17 92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side