Form 3160-5				
(June 1990)	DEPARTME	ITED STATES NT OF THE INTERIOR	ំ ខ្លះ ខ្លះ ខ្លះ រ ប្រើខ្លាំ ទី រំ ស្លែ	FORM APPROVED Budget Bureau No. 1001-0135
		LAND MANAGEMENT	ing in the second se	EXDITES' March 11 1003
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals				5. Lease Designation and Serial No. USA NM-153()3 6. If Indian, Allottee or Tribe Name
		IN TRIPLICATE	sals	-
I. Type of Well Oil Gas Well Well				7. If Unit or CA, Agreement Designation
2. Name of Operator	Other			8. Well Name and No.
Bettis, Boyle & Stovall 3 Address and Telephone No.				PICKett Draw Fed #3
P. O. Box 1240, Graham, TX 76450 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				30-015-26880
				10. Field and Pool, or Exploratory Area Wildcat (Delaware)
582' fSL & 738' FWL Sec 10, T25S, R29E				E i i i i i i i i i i i i i i i i i i i
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO				
			TYPE OF ACTION	T, OR OTHER DATA
Notice of Inte				[]
X Subsequent R	cport	Recompletion		Change of Plans
		Plugging Back		New Construction
Final Abandor	nment Notice	Casing Repair Altering Casing		Water Shut-Off
		X Other	production	Conversion to Injection
Describe Proposed or Complete	d One of the second s			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form ) proposed work. If well is directionally drilled,
			- orky	
1/5/92 Run	tubing and rods Set pumping un or first product	in well. Bottom of 2- it and put well on pum		
1/5/92 Run	tubing and rods Set pumping un or first product	in well. Bottom of 2- it and put well on pum ion on well.		
1/5/92 Run	tubing and rods Set pumping un or first product	in well. Bottom of 2- it and put well on pum ion on well.		
1/5/92 Run	tubing and rods Set pumping un or first product	in well. Bottom of 2- it and put well on pum ion on well.		
1/5/92 Run	tubing and rods Set pumping un or first product	in well. Bottom of 2- it and put well on pum ion on well.		
1/5/92 Run	tubing and rods Set pumping un or first product	in well. Bottom of 2- it and put well on pum ion on well.		
1/5/92 Run	tubing and rods Set pumping un or first product	in well. Bottom of 2- it and put well on pum ion on well.		090'; space well ping well at 6:00
1/5/92 Run		ion on we]].		
1/5/92 Run tout. pm fo		in well. Bottom of 2- it and put well on pum ion on well.		090'; space well ping well at 6:00
1/5/92 Run out. pm fc	is, true and correct Kim Ligon	ion on we]].	7/8" tubing @ g	1090'; space well ping well at 6:00
1/5/92 Run out. pm fc reby certify that he horeeomen ed s space for Federal or State offi	is, true and correct Kim Ligon	Title Production Analys	7/8" tubing @ g	090'; space well ping well at 6:00
1/5/92 Run Out. pm fc pm fc space for Federal or State offi	is, true and correct Kim Ligon	Ion on well.	7/8" tubing @ g p. Started pur st	1090'; space well ping well at 6:00
1/5/92 Run out. pm fc reby certily that the horeeoneri ed s space for Federal or State offi oved by itions of approval, if any:	is, true) and correct Kim Ligon	Title Production Analys	7/8" tubing @ g	090'; space well ping well at 6:00 1992 225 Date