

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Pogo Producing Company

3. Address and Telephone No.
P. O. Box 10340, Midland TX 79702-7340

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
330' FNL and 990' FWL, Section 1, T-24-S, R-31-E

5. Lease Designation and Serial No.

NM-69369

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Sundance 1 Federal No. 2

9. API Well No.

30-015-27227

10. Field and Pool, or Exploratory Area

Mesa Verde - Del

11. County or Parish, State

Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 11" hole 583' to 4360'. TD reached @ 0200 hrs CDT 5/21/96. Ran 98 jts 8-5/8", 24# & 32#, J-55 ST&C casing. Float shoe @ 4360'. Float collar @ 4313'. Howco cemented with 1350 sx Halliburton Lite @ 12.7 ppg followed by 200 sx Premium Plus @ 14.8 ppg. Plug down @ 1415 hrs CDT 5/21/96. Recovered 100 sx excess cement. ND BOP's and make cut-off. Weld on wellhead and test to 1500 psi. NU BOP's and test to 1500 psi.

14. I hereby certify that the foregoing is true and correct

Signed Banda Smith Title Senior Operations Engineer

Date 6/21/96

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____ Date _____